#### Facility Summary in Missoula County in the City of Bonner

Location: JMBC INC

29344 MT Hwy 200 E

Bonner, MT 59823-9526 Missoula

System Facility ID:32-12400

Facility Code: 25677
Last Inspected On: 11/06/2019
Operating Permit Renewal Date: 04/19/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: JMBC Inc Bonner 4062443100

Operator Contact:Doug Zimmerman; Jim Fry; Joe Johnson4062443100; 4062613569

Owner/Operator: JMBC Inc Bonner

Doug Zimmerman, UST Class A Operator Doug Zimmerman, UST Class B Operator Jim Fry, UST Class A Operator Jim Fry, UST Class B Operator Joe Johnson, UST Class B Operator Joe Johnson, UST Class B Operator

Tank Code	01	Tank Age	31	Tank Installed Date	05/28/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	3488	Spill Test Date	06/10/2020	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/09/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	11/06/2019	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/10/2020			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				
Tank Code	02	Tank Age	31	Tank Installed Date	05/28/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	3489	Spill Test Date	06/10/2020	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/09/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No

Report Created: 11/1/2022 Page [1] of [147]

Capacity	4000	ATG Test Date		Line Tightness Test Date	11/06/2019	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/10/2020			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				
Tank Code	03	Tank Age	31	Tank Installed Date	05/28/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	3490	Spill Test Date	06/10/2020	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/09/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	11/06/2019	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/10/2020			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				
Tank Code	04	Tank Age	31	Tank Installed Date	05/28/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve;Flapper Valve
Tag Number	3491	Spill Test Date	06/10/2020	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/09/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	3000	ATG Test Date		Line Tightness Test Date	10/20/2010	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	06/10/2020			ATG Type	Gilbarco/EMC Basic				

# Facility Summary in Missoula County in the City of Clinton

Location: BEARMOUTH EXPRESS 16595 US Hwy 10 E Clinton, MT 59825-9678 Missoula

Facility Code: 25223 Last Inspected On: 07/20/2022 Operating Permit Renewal Date: 11/12/2025

System Facility ID:32-01572

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Gene Tripp 4068254000

Operator Contact: Bryan Tripp;Jeff Tripp 4068254000

Page [2] of [147] Report Created: 11/1/2022

Owner/Operator: Gene Tripp

Bryan Tripp, UST Class A Operator Bryan Tripp, UST Class B Operator Jeff Tripp, UST Class A Operator Jeff Tripp, UST Class B Operator

Tank Code	01	Tank Age	43	Tank Installed Date	04/29/1979		Cathodically Protected Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	1205	Spill Test Date	07/20/2022	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	07/20/2022	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/20/2022			ATG Type					

## Facility Summary in Missoula County in the City of Clinton

Location: CLINTON MARKET

20500 Hwy 10 E

Clinton, MT 59825 Missoula

Facility Code: 30695 Last Inspected On: 12/08/2021

Operating Permit Renewal Date: 04/09/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Clinton Market Inc;Roy Handley;Clinton Market Inc;RR

Investments of Montana

4065464940

System Facility ID:56-14040

Operator Contact: Roy Handley

4065464940

Owner/Operator: Clinton Market Inc

Owner/Operator: Roy Handley, Clinton Market Inc

Owner/Operator: RR Investments of Montana

Roy Handley, UST Class A Operator Roy Handley, UST Class B Global Operator

Tank Code	01	Tank Age	20	Tank Installed Date	05/16/2002	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4651	Spill Test Date	12/08/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No

Page [3] of [147] Report Created: 11/1/2022

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	12/08/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date	12/08/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date	05/18/2022			ATG Type	Gilbarco/TLS- 350;Veeder Root/				
Tank Code	02	Tank Age	20	Tank Installed Date	05/16/2002	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4652	Spill Test Date	12/08/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	12/08/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	12/08/2021	Line Tightness Test Date	02/26/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/18/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/				
Tank Code	03	Tank Age	20	Tank Installed Date	05/16/2002	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4653	Spill Test Date	12/08/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	12/08/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	5000	ATG Test Date	12/08/2021	Line Tightness Test Date	02/28/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/18/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/				
Tank Code	04	Tank Age	13	Tank Installed Date	10/29/2009	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	5223	Spill Test Date	12/08/2021	Piping Installed Date	10/14/2009	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	12/08/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date	12/08/2021	Line Tightness Test Date	02/26/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

		Overfill Test Date	12/08/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/				
Tank Code	05	Tank Age	4	Tank Installed Date	08/28/2018	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	5851	Spill Test Date	12/08/2021	Piping Installed Date	08/28/2018	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	08/29/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	12/08/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	6000	ATG Test Date	12/08/2021	Line Tightness Test Date	02/26/2019	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	12/08/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/				

## Facility Summary in Missoula County in the City of Clinton

Location: ROCK CREEK LODGE 7 Rock Creek Rd

Clinton, MT 59825 Missoula

Facility Code: 25616 Last Inspected On: 01/08/2021

System Facility ID:32-11093

Operating Permit Renewal Date: 01/08/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Rock Creek Lodge LLC 4068254868

Operator Contact:

Owner/Operator: Rock Creek Lodge LLC

Tank Code	03	Tank Age	28	Tank Installed Date	05/01/1994	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	4572	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.1;Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [5] of [147]

		Overfill Test Date				ATG Type	Veeder Root/TLS- 300				
Tank Code	04	Tank Age	28	Tank Installed Date	05/01/1994	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	4573	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date	09/20/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS- 300				

## Facility Summary in Missoula County in the City of Condon

Location: MISSION MOUNTAINS MERCANTILE

7217 MT Hwy 83 Condon, MT 59826 Missoula

System Facility ID:32-01619

Facility Code: 25226 Last Inspected On: 06/10/2020 Operating Permit Renewal Date: 06/10/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Leonard Kobylenski 4067542387

Operator Contact: Leonard Kobylenski 4067542387

Owner/Operator: Len Kobylenski

Len Kobylenski, UST Class A Operator Len Kobylenski, UST Class B Operator

Tank Code	04	Tank Age	30	Tank Installed Date	05/20/1992	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	High Level Alarm
Tag Number	1495	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/28/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date	07/28/2021	Line Tightness Test Date	04/17/2018	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/28/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Page [6] of [147] Report Created: 11/1/2022

Tank Code	05	Tank Age	30	Tank Installed Date	05/20/1992	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	High Level Alarm
Tag Number	1496	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/28/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date	07/28/2021	Line Tightness Test Date	04/17/2018	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/28/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	06	Tank Age	30	Tank Installed Date	05/20/1992	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	High Level Alarm
Tag Number	1497	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/28/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date	07/28/2021	Line Tightness Test Date	04/17/2018	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
							Gilbarco-Veeder				

Report Created: 11/1/2022 Page [7] of [147]

## Facility Summary in Missoula County in the City of Frenchtown

Location: BRONCS GROCERIES INC

16640 Beckwith St

Frenchtown, MT 59834-9747 Missoula

System Facility ID:32-05767

Facility Code: 25384
Last Inspected On: 02/19/2021
Operating Permit Renewal Date: 03/03/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Jeremy Louvar 4065463656

Operator Contact:

Owner/Operator: Jeremy Louvar

Jeremy Louvar, UST Class B Operator

Tank Code	04	Tank Age	24	Tank Installed Date	05/01/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	2702	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	04/21/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/21/2022	Line Tightness Test Date	01/07/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	04/21/2022			ATG Type	Gilbarco/EMC Basic				
Tank Code	05	Tank Age	24	Tank Installed Date	05/01/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	2703	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	04/21/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date	04/21/2022	Line Tightness Test Date	01/07/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	04/21/2022			ATG Type	Gilbarco/EMC				

Facility Summary in Missoula County in the City of Frenchtown

Report Created: 11/1/2022 Page [8] of [147]

Location: FRENCHIES

16875 Beckwith St

Frenchtown, MT 59834-9646 Missoula

System Facility ID:32-11177

Facility Code: 25623 Last Inspected On: 05/18/2022 Operating Permit Renewal Date: 11/01/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Tabish Brothers Distributors Inc 4065437621

Operator Contact: Alivia Moseman; Joe Heuchert; Karly Shafer 4063962206

# Owner/Operator: Tabish Brothers Distributors Inc

Alivia Moseman, UST Class A Operator Alivia Moseman, UST Class B Global Operator Heather Stiles, UST Class B Global Operator Joe Heuchert, UST Class A Operator Karly Shafer, UST Class B Global Operator

Tank Code	05	Tank Age	32	Tank Installed Date	06/25/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	4372	Spill Test Date	05/18/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	05/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	05/18/2022	Line Tightness Test Date	05/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/18/2022			ATG Type	Veeder Root/Red Jacket FXIV;Veeder Root/TLS-300				
Tank Code	06	Tank Age	32	Tank Installed Date	06/25/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	4373	Spill Test Date	05/18/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	05/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	05/18/2022	Line Tightness Test Date	05/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [9] of [147]

		Overfill Test Date	05/18/2022			ATG Type	Veeder Root/Red Jacket FXIV;Veeder Root/TLS-300				
Tank Code	07	Tank Age	32	Tank Installed Date	06/25/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	4374	Spill Test Date	05/18/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	05/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date	05/18/2022	Line Tightness Test Date	05/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/18/2022			ATG Type	Veeder Root/Red Jacket FXIV;Veeder Root/TLS-300				
Tank Code	08	Tank Age	32	Tank Installed Date	06/25/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	4375	Spill Test Date	05/18/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	05/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date	05/18/2022	Line Tightness Test Date	05/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/18/2022			ATG Type	Vaporless Manufacturing/Va porless LD- 2000;Veeder Root/TLS-300				

# Facility Summary in Missoula County in the City of Greenough

Location: CLEARWATER STOP N GO

44676 MT Hwy 200 E Greenough, MT 59823-9557 Missoula

System Facility ID:32-07114

Facility Code: 25422 Last Inspected On: 03/18/2022 Operating Permit Renewal Date: 06/24/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: The Cow Group 4063968431

Operator Contact: Jeff Stavish; Sherri Housley 4062445598

Page [10] of [147] Report Created: 11/1/2022

# Owner/Operator: The Cow Group

Jeff Stavish, UST Class A Operator Jeff Stavish, UST Class B Global Operator Sherri Housley, UST Class A Operator Sherri Housley, UST Class B Operator

Tank Code	04	Tank Age	23	Tank Installed Date	04/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4474	Spill Test Date	10/12/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/18/2022	Line Tightness Test Date	03/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	10/12/2021			ATG Type	Gilbarco/EMC Basic				
Tank Code	05	Tank Age	23	Tank Installed Date	04/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4475	Spill Test Date	10/12/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date	03/18/2022	Line Tightness Test Date	03/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	10/12/2021			ATG Type	Gilbarco/EMC Basic				
Tank Code	06	Tank Age	23	Tank Installed Date	04/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4476	Spill Test Date	10/12/2021	Piping Installed Date	03/19/2018	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/18/2022	Sump Tightness Test Date	08/12/2022	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/18/2022	Line Tightness Test Date	03/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	Yes
		Overfill Test Date	10/12/2021			ATG Type	Gilbarco/EMC Basic				

Report Created: 11/1/2022 Page [11] of [147]

#### Facility Summary in Missoula County in the City of Lolo

Location: LOLO SUPERSTOP 12011 US Hwy 93 S

Lolo, MT 59847-9666 Missoula

Facility Code: 30482 Last Inspected On: 06/30/2022

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Tabish Brothers Distributors Inc 4065437621

Operator Contact: Bri Mader; Karly Shafer 4063962206

Owner/Operator: Tabish Brothers Distributors Inc

Bri Mader, UST Class A Operator Bri Mader, UST Class B Operator Karly Shafer, UST Class A Operator Karly Shafer, UST Class B Global Operator

Tank Code	05	Tank Age	24	Tank Installed Date	01/15/1998	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2086	Spill Test Date	06/30/2022	Piping Installed Date	12/01/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	09/16/2016	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	06/15/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date	06/15/2022	Line Tightness Test Date	04/27/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	06	Tank Age	24	Tank Installed Date	01/15/1998	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2087	Spill Test Date	06/30/2022	Piping Installed Date	12/01/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	09/16/2016	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	06/15/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date	06/15/2022	Line Tightness Test Date	05/01/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No

Report Created: 11/1/2022 Page [12] of [147]

		Overfill Test Date			Ī	ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				[
Tank Code	07	Tank Age	24	Tank Installed Date	01/15/1998	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2088	Spill Test Date	06/30/2022	Piping Installed Date	12/01/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	09/16/2016	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel, Dyed	PLLD Test Date	06/15/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date	06/15/2022	Line Tightness Test Date	05/07/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	08	Tank Age	24	Tank Installed Date	01/15/1998	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2089	Spill Test Date	06/30/2022	Piping Installed Date	12/01/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	09/16/2016	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	06/15/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date	06/15/2022	Line Tightness Test Date	05/07/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	09	Tank Age	24	Tank Installed Date	01/15/1998	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2090	Spill Test Date	06/30/2022	Piping Installed Date	12/01/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	09/16/2016	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	06/15/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date	06/15/2022	Line Tightness Test Date	05/01/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Facility Summary in Missoula County in the City of Lolo

Report Created: 11/1/2022 Page [13] of [147]

Location: TOWN PUMP INC LOLO 1 10955 US Hwy 93 S Lolo, MT 59847 Missoula

System Facility ID:32-09414

Facility Code: 25493
Last Inspected On: 08/03/2021
Operating Permit Renewal Date: 11/01/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Lolo 1 Town Pump LLC 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Lolo 1 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	05	Tank Age	1	Tank Installed Date	04/20/2021	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	6029	Spill Test Date	03/10/2021	Piping Installed Date	04/20/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	20000	ATG Test Date		Line Tightness Test Date	05/04/2021	Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	03/02/2021			ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	06	Tank Age	1	Tank Installed Date	04/20/2021	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	6030	Spill Test Date	03/10/2021	Piping Installed Date	04/20/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	15000	ATG Test Date		Line Tightness Test Date	05/04/2021	Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes

Report Created: 11/1/2022 Page [14] of [147]

		Overfill Test Date	03/02/2021			ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	07	Tank Age	1	Tank Installed Date	04/20/2021	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	6031	Spill Test Date	03/10/2021	Piping Installed Date	04/20/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	7000	ATG Test Date		Line Tightness Test Date	05/04/2021	Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	03/02/2021			ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	08	Tank Age	1	Tank Installed Date	04/20/2021	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	6032	Spill Test Date	03/10/2021	Piping Installed Date	04/20/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date	05/04/2021	Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	03/02/2021			ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	09	Tank Age	1	Tank Installed Date	04/20/2021	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	6033	Spill Test Date	03/10/2021	Piping Installed Date	04/20/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No

Report Created: 11/1/2022 Page [15] of [147]

Capacity	7000	ATG Test Date		Line Tightness Test Date	05/04/2021	Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	03/02/2021			ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				

## Facility Summary in Missoula County in the City of Lolo

Location: TOWN PUMP INC LOLO 2

11882 US Hwy 93 S Lolo, MT 59847-9567 Missoula

Facility Code: 25228 Last Inspected On: 05/03/2021

System Facility ID:32-01639 Operating Permit Renewal Date: 05/07/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Lolo 2 Town Pump LLC 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Lolo 2 Town Pump LLC

Trent Biggers, UST Class A Operator Trent Biggers, UST Class B Global Operator

Tank Code	13	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2545	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date	12/05/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	14	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2546	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Page [16] of [147] Report Created: 11/1/2022

Product	Diesel	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date	12/05/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	17	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2549	Spill Test Date		Piping Installed Date	08/11/2013	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date	12/05/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	18	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2550	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date	12/05/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	15	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4289	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date	12/05/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [17] of [147]

		Overfill Test Date	[		[	ATG Type	Gilbarco-Veeder Root/TLS-350				[
Tank Code	16	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4290	Spill Test Date		Piping Installed Date	08/11/2013	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date	12/05/2012	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	20	Tank Age	18	Tank Installed Date	09/15/2004	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4942	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	21	Tank Age	18	Tank Installed Date	09/15/2004	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4943	Spill Test Date		Piping Installed Date	08/11/2013	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/03/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/03/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Facility Summary in Missoula County in the City of Lolo

Report Created: 11/1/2022 Page [18] of [147]

Location: TRAVELS REST COUNTRY STORE

10565 Lolo Creek Rd Lolo, MT 59847-9471 Missoula

System Facility ID:32-11303

Facility Code: 25632 Last Inspected On: 11/02/2021 Operating Permit Renewal Date: 12/12/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Travels Rest Country Store

Operator Contact: Glen Doty;Steve Mortenson;Terri Sullivan 4062732037

# Owner/Operator: Travels Rest Country Store

Glen Doty, UST Class A Operator Glen Doty, UST Class B Operator Steve Mortenson, UST Class A Operator Steve Mortenson, UST Class B Operator Terri Sullivan, UST Class A Operator Terri Sullivan, UST Class B Operator

Tank Code	S4	Tank Age	19	Tank Installed Date	08/13/2003	Tank Material	Concrete	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4854	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/02/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	11/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	S5	Tank Age	19	Tank Installed Date	08/13/2003	Tank Material	Concrete	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4855	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/02/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	11/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [19] of [147]

		Overfill Test Date			[	ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	S6	Tank Age	19	Tank Installed Date	06/23/2003	Tank Material	Concrete	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4856	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/02/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	11/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	S7	Tank Age	19	Tank Installed Date	06/23/2003	Tank Material	Concrete	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4857	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/02/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	11/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	S8	Tank Age	19	Tank Installed Date	06/23/2003	Tank Material	Concrete	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4858	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	11/02/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	11/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Facility Summary in Missoula County in the City of Milltown

Report Created: 11/1/2022 Page [20] of [147]

Location: TOWN PUMP INC BONNER-MILLTOWN

7985 MT Hwy 200 E Milltown, MT 59851 Missoula

System Facility ID:32-13629

Facility Code: 25772
Last Inspected On: 05/11/2021
Operating Permit Renewal Date: 05/14/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

 Owner Operator Contact:
 Bonner Town Pump and Casino Inc
 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Bonner Town Pump and Casino Inc

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	01	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2564	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	05	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2568	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [21] of [147]

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	07	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2570	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	08	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2571	Spill Test Date		Piping Installed Date	10/17/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	09	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2572	Spill Test Date		Piping Installed Date	10/17/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No

Report Created: 11/1/2022 Page [22] of [147]

Capacity	10000	ATG Test Date	[	Line Tightness Test Date	[	Secondary Tank Leak Detection	Continuous Interstitial	Secondary Pipe Detection	Statistical Inventory	Energy Act	No
		Overfill Test Date				ATG Type	Monitoring Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD		Reconciliation		
Tank Code	11	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2574	Spill Test Date		Piping Installed Date	10/17/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	02	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	4260	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	03	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	4261	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Report Created: 11/1/2022 Page [23] of [147]

Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
	Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
04	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
4262	Spill Test Date		Piping Installed Date	10/13/2006	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
	Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
06	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
4263	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/19/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
	Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
12	Tank Age	19	Tank Installed Date	12/03/2003	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
4871	Spill Test Date		Piping Installed Date	10/17/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
	12000  04  4262  Currently in Use  Diesel  12000  06  4263  Currently in Use  Diesel  12000	Overfill Test Date  Overfill Test Date  Overfill Test Date  Tank Age  4262 Spill Test Date  Currently in WLLD Test Date  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Currently in WLLD Test Date  OF Tank Age  4263 Spill Test Date  Currently in WLLD Test Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Overfill Test Date  Tank Age  12000 ATG Test Date	Overfill Test Date  Overfill Test Date  O4 Tank Age 27  4262 Spill Test Date  Currently in Use MLLD Test Date  Diesel PLLD Test Date 05/09/2021  12000 ATG Test Date  Overfill Test Date  Currently in Use 27  4263 Spill Test Date  Currently in MLLD Test Date  Diesel PLLD Test Date  O5/09/2021  12000 ATG Test Date  Diesel PLLD Test Date  O5/09/2021  12000 ATG Test Date  Overfill Test Date	12000 ATG Test Date  Overfill Test Date  Overfill Test Date  Overfill Test Date  Tank Installed Date  Currently in Use  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Diesel PLLD Test Date  Tank/Piping CP Test Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Tank/Piping CP Test Date  Diesel PLLD Test Date  Tank/Piping CP Test Date	Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Diate  Overfill Test Date  Diate  Currently in Use  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Diesel PLLD Test Date  Overfill Test Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Test Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Test Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Test Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Test Date  Diesel Date  Diesel PLLD Test Date  Diesel PLLD Test Date  Diesel Date  Diesel PLLD Test Date  Diesel Date  Diesel PLLD Test Date  Diesel Date	Diesel   PLLD Test Date   Display   Diesel   D	Diesel   PLLD Test Date   05/09/2021   Test Date   Ceah Detection   Reconciliation   Reco	PLLD Test Date   05/09/2021   Tank/riping Prest Date   Lank Detection   Reconciliation   Private Private   Private Pri	Diesel   PLLD Test Date   05/09/2021   Test Date   Care Detection   Care	Pillade   Pillade   Score   Pillade   Score   Pillade   Pillade

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	13	Tank Age	19	Tank Installed Date	12/03/2003	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4872	Spill Test Date		Piping Installed Date	10/17/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	10	Tank Age	27	Tank Installed Date	09/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	4889	Spill Test Date		Piping Installed Date	10/17/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	14	Tank Age	9	Tank Installed Date	06/01/2013	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5363	Spill Test Date		Piping Installed Date	07/12/2013	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Other	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0		Piping Type	Pressurized	CP Met Types	

Report Created: 11/1/2022 Page [25] of [147]

Product	DEF (Not Regulated)	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring;Deferr ed	Primary Pipe Detection	Continuous Interstitial Monitoring;Deferre d	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	15	Tank Age	4	Tank Installed Date	01/01/2018	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Positive Shutoff
Tag Number	5802	Spill Test Date		Piping Installed Date	12/22/2017	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/09/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-450				

#### Facility Summary in Missoula County in the City of Missoula

Location: 3RD STREET MART

2340 S 3rd St W

Missoula, MT 59801 Missoula

Facility Code: 25246

Last Inspected On: 06/22/2022

System Facility ID:32-02179

Operating Permit Renewal Date: 08/28/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Jays Corporation

Operator Contact: Charles Weight; Jagpreet Ghuman; John McKay; Justin McKay 4062074884; 4062931873; 4065420550; 4068807677

# Owner/Operator: Jays Corporation

Amy Williams, UST Class B Operator Charles Weight, UST Class A Operator Charles Weight, UST Class B Operator Jagpreet Ghuman, UST Class A Operator John McKay, UST Class A Operator John McKay, UST Class B Operator Justin McKay, UST Class B Operator Justin McKay, UST Class B Operator

Report Created: 11/1/2022 Page [26] of [147]

Tank Code	01	Tank Age	46	Tank Installed Date	04/23/1976	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	3624	Spill Test Date	04/27/2021	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	01/17/2022	Tank/Piping CP Test Date	04/13/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	01/17/2022	Line Tightness Test Date	04/01/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	01/17/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/8484 Series PLLD				
Tank Code	02	Tank Age	46	Tank Installed Date	04/23/1976	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	3625	Spill Test Date	04/27/2021	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	01/17/2022	Tank/Piping CP Test Date	04/13/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	01/17/2022	Line Tightness Test Date	04/07/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	01/17/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	46	Tank Installed Date	04/23/1976	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	3626	Spill Test Date	04/27/2021	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	01/17/2022	Tank/Piping CP Test Date	04/13/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date	01/17/2022	Line Tightness Test Date	10/11/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [27] of [147]

# Overfill Test Date 01/17/2022 ATG Type Gilbarco-Veeder Root/TLS-350;Veeder Root/8484 Series PLLD

# Facility Summary in Missoula County in the City of Missoula

Location: AIRWAY FLEET FUEL 5355 W Harrier

Missoula, MT 59808 Missoula

Facility Code: 30771 Last Inspected On: 09/29/2019

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Finest Oil Co 4065436969

Operator Contact: Christopher Glasser; James Brady; John Stordahl; Justin

Gaudot;Stephen Hanson

4062181563;4065436969;4065441005;7143338926

Owner/Operator: Finest Oil Co

Christopher Glasser, UST Class A Operator
James Brady, UST Class A Operator
John Stordahl, UST Class A Operator
Joseph McClain, UST Class B Operator
Justin Gaudot, UST Class A Operator
Justin Gaudot, UST Class B Global Operator

Stephen Hanson, UST Class A Operator Stephen Hanson, UST Class B Operator

Tank Code	01	Tank Age	17	Tank Installed Date	04/05/2005	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4904	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	06/12/2013	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				

Report Created: 11/1/2022 Page [28] of [147]

Tank Code	02	Taula A ma	4.7	Tank Installed	04/05/0005	Taul Matarial	Fiberglass	Dining Material	Flavible Blastic	Overetill Transpor	Dall Flact Value
		Tank Age	17	Date	04/05/2005	Tank Material	Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4905	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	15000	ATG Test Date		Line Tightness Test Date	06/12/2013	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	17	Tank Installed Date	04/05/2005	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4906	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	06/12/2013	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	04	Tank Age	17	Tank Installed Date	04/05/2005	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4907	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	25000	ATG Test Date		Line Tightness Test Date	06/12/2013	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [29] of [147]

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	05	Tank Age	17	Tank Installed Date	04/05/2005	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5038	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	06/12/2013	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				

# Facility Summary in Missoula County in the City of Missoula

Location: ALLIED WASTE SERVICES OF NORTH AMERICA LLC

1501 Rodgers St Missoula, MT 59802-1735 Missoula

System Facility ID:32-09872

Facility Code: 25524 Last Inspected On: 07/15/2020 Operating Permit Renewal Date: 08/30/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Allied Waste Services of North America LLC 4065433157

Operator Contact: David Seeberger 4065433157

Owner/Operator: Allied Waste Services of North America LLC

David Seeberger, UST Class A Operator David Seeberger, UST Class B Global Operator

Tank Code	04	Tank Age	32	Tank Installed Date	01/24/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm
Tag Number	500	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	07/15/2020	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic

Page [30] of [147] Report Created: 11/1/2022

Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	07/15/2020	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	05	Tank Age	32	Tank Installed Date	01/24/1990	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	501	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	07/15/2020	Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date	07/15/2020	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	2000	ATG Test Date		Line Tightness Test Date	07/18/2006	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Report Created: 11/1/2022 Page [31] of [147]

# Facility Summary in Missoula County in the City of Missoula

Location: BEACH TRANSPORTATION CO

825 Mount Ave

Missoula, MT 59801-5607 Missoula

System Facility ID:32-11904

Facility Code: 25660
Last Inspected On: 03/17/2022
Operating Permit Renewal Date: 05/20/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Beach Transportation 4065496121

Operator Contact: Carlin Cavill;Scott Beach 4065496121

Owner/Operator: Beach Transportation

Carlin Cavill, UST Class A Operator Carlin Cavill, UST Class B Operator Scott R Beach, UST Class A Operator

Tank Code	03	Tank Age	25	Tank Installed Date	09/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2361	Spill Test Date	03/17/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/17/2022	Sump Tightness Test Date	03/17/2022	Catastrophic L.D Type 3.0	Auto Dialer;Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/17/2022	Line Tightness Test Date	03/03/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	03/17/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Vaporless Manufacturing/Va porless 99LD- 2000				

#### Facility Summary in Missoula County in the City of Missoula

System Facility ID:60-15296

Location: CHS MISSOULA PETROLEUM TERMINAL

3576 Grant Creek Rd

Missoula, MT 59808 Missoula

Facility Code: 31000 Last Inspected On: 09/20/2022

Operating Permit Renewal Date: 01/17/2026

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Report Created: 11/1/2022 Page [32] of [147]

4066285200

Operator Contact: Matthew Mill 4067213207

Owner/Operator: CHS Inc Laurel

Matthew Mill, UST Class A Operator Matthew Mill, UST Class B Operator

Tank Code	01	Tank Age	14	Tank Installed Date	02/01/2008	Tank Material	Not Listed	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	5708	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Mixture	PLLD Test Date		Tank/Piping CP Test Date	08/03/2022	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	7750	ATG Test Date		Line Tightness Test Date	06/22/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

# Facility Summary in Missoula County in the City of Missoula

Location: CIRCLE K STORE 2746282

605 S Higgins Ave

Missoula, MT 59801-2733 Missoula

System Facility ID:32-09733

Facility Code: 25517 Last Inspected On: 02/21/2020 Operating Permit Renewal Date: 08/17/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Rocky Mountain Oil LLC 6027288000

Operator Contact: Veronica Rivera

Owner/Operator: Rocky Mountain Oil LLC

Brad Lee, UST Class B Global Operator Jeff Reed, UST Class B Global Operator Veronica Rivera, UST Class A Operator

Tank	Code	01	Tank Age	34	Tank Installed Date	08/01/1988	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag N	lumber	3028	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No

Report Created: 11/1/2022 Page [33] of [147]

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/25/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date	09/16/2019	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	02	Tank Age	34	Tank Installed Date	08/01/1988	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3029	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/25/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date	01/26/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	34	Tank Installed Date	08/01/1988	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3030	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/25/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date	01/28/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				

Facility Summary in Missoula County in the City of Missoula

Report Created: 11/1/2022 Page [34] of [147]

Location: CIRCLE K STORE2746278

403 S Russell St

Missoula, MT 59801-2311 Missoula

System Facility ID:32-08072

Facility Code: 25460 Last Inspected On: 11/08/2021 Operating Permit Renewal Date: 04/23/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Rocky Mountain Oil LLC 6027288000

Operator Contact: Veronica Rivera

Owner/Operator: Rocky Mountain Oil LLC

Brad Lee, UST Class B Global Operator Jeff Reed, UST Class B Global Operator Veronica Rivera, UST Class A Operator

Tank Code	06	Tank Age	27	Tank Installed Date	07/31/1995	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3024	Spill Test Date	01/17/2019	Piping Installed Date	06/10/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/25/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	01/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date	01/12/2021	Line Tightness Test Date	07/25/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date	01/17/2019			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	07	Tank Age	27	Tank Installed Date	07/31/1995	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3025	Spill Test Date	01/17/2019	Piping Installed Date	06/10/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/25/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	01/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	8000	ATG Test Date	01/12/2021	Line Tightness Test Date	07/27/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date	01/17/2019			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Report Created: 11/1/2022 Page [35] of [147]

Tank Code	08	Tank Age	27	Tank Installed Date	07/31/1995	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3026	Spill Test Date	01/17/2019	Piping Installed Date	06/10/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/25/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	01/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	8000	ATG Test Date	01/12/2021	Line Tightness Test Date	08/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date	01/17/2019			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	09	Tank Age	27	Tank Installed Date	07/31/1995	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4700	Spill Test Date	01/17/2019	Piping Installed Date	06/10/2021	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/25/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	01/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	12000	ATG Test Date	01/12/2021	Line Tightness Test Date	10/13/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date	01/17/2019			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

# Facility Summary in Missoula County in the City of Missoula

**Location:** CIRLCE K STORE 2746283 2325 S Reserve St

Missoula, MT 59801-6446 Missoula

System Facility ID:32-09694

Facility Code: 25512 Last Inspected On: 12/01/2020 Operating Permit Renewal Date: 02/13/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Rocky Mountain Oil LLC 6027288000

Operator Contact: Veronica Rivera

Owner/Operator: Rocky Mountain Oil LLC

Brad Lee, UST Class B Global Operator Jeff Reed, UST Class B Global Operator Veronica Rivera, UST Class A Operator

Report Created: 11/1/2022 Page [36] of [147]

Tank Code	01	Tank Age	35	Tank Installed Date	08/01/1987	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3706	Spill Test Date		Piping Installed Date	04/10/2019	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/15/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	06/10/2020	Tank/Piping CP Test Date	12/01/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date	07/06/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				
Tank Code	02	Tank Age	35	Tank Installed Date	08/01/1987	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3707	Spill Test Date		Piping Installed Date	04/10/2019	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/15/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	06/10/2020	Tank/Piping CP Test Date	12/01/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	10000	ATG Test Date		Line Tightness Test Date	06/14/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				
Tank Code	03	Tank Age	35	Tank Installed Date	08/01/1987	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3708	Spill Test Date		Piping Installed Date	04/10/2019	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/15/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	06/10/2020	Tank/Piping CP Test Date	12/01/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	10000	ATG Test Date		Line Tightness Test Date	06/17/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				

Report Created: 11/1/2022 Page [37] of [147]

Tank Code	04	Tank Age	35	Tank Installed Date	08/01/1987	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3709	Spill Test Date		Piping Installed Date	04/10/2019	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	03/15/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	06/10/2020	Tank/Piping CP Test Date	12/01/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	06/13/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				

Location: COMMUNITY MEDICAL CENTER

2827 Fort Missoula Rd Missoula, MT 59804 Missoula

System Facility ID:32-11740

Facility Code: 25652 Last Inspected On: 12/02/2020 Operating Permit Renewal Date: 03/08/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: RCHP Billings - Missoula LLC

Operator Contact:

Owner/Operator: RCHP Billings - Missoula LLC

Steve Martin, UST Class B Operator

Tank Code	04	Tank Age	28	Tank Installed Date	07/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2353	Spill Test Date	12/01/2020	Piping Installed Date	06/03/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/22/2017	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	U.S. Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	12/01/2020	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	12/02/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	3-Year Line Tightness Test	Energy Act	No
		Overfill Test Date	12/02/2020			ATG Type	Gilbarco-Veeder Root/ILS-250				

Report Created: 11/1/2022 Page [38] of [147]

Location: COSTCO WHOLESALE FUELING FACILITY

3220 N Reserve St

Missoula, MT 59808-1556 Missoula

System Facility ID:56-13977

Facility Code: 30639
Last Inspected On: 10/26/2021
Operating Permit Renewal Date: 02/15/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Costco Wholesale 4252516222

Operator Contact: Brandon Krause;Dan Walsh;Denise Parrott;Lance

Philliber; Shane Meeker; Shawn Willis; Wayne Rhoades

4065239982;4065436445

Owner/Operator: Costco Wholesale

Brandon Krause, UST Class A Operator

Brett Smith, UST Class B Operator

Dan Walsh, UST Class A Operator

Denise Parrott, UST Class A Operator

Lance Philliber, UST Class A Operator

Shane Meeker, UST Class A Operator

Shawn Willis, UST Class A Operator

Shawn Willis, UST Class B Global Operator

Shawn Willis, UST Class B Operator

Wayne Rhoades, UST Class A Operator

Tank Code	01	Tank Age	22	Tank Installed Date	05/15/2000	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4189	Spill Test Date	06/04/2019	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/21/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	07/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date	07/12/2021	Line Tightness Test Date	07/12/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/12/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/8484 Series PLLD				
Tank Code	02	Tank Age	22	Tank Installed Date	05/15/2000	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm

Report Created: 11/1/2022 Page [39] of [147]

Tag Number	4190	Spill Test Date	06/04/2019	Piping Installed Date	[	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/21/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	07/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date	07/12/2021	Line Tightness Test Date	07/12/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/12/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	22	Tank Installed Date	05/15/2000	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4191	Spill Test Date	06/04/2019	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/21/2019	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	07/12/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date	07/12/2021	Line Tightness Test Date	07/12/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/12/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/8484 Series PLLD				
Tank Code	04	Tank Age	11	Tank Installed Date	08/01/2011	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve;High Level Alarm
Tag Number	5283	Spill Test Date	06/04/2019	Piping Installed Date	10/25/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/12/2021	Sump Tightness Test Date	06/21/2019	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Hazardous Substance	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	1500	ATG Test Date	11/15/2021	Line Tightness Test Date	07/12/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	Yes
		Overfill Test Date	11/15/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Vaporless Manufacturing/Va porless LD-2000				

Report Created: 11/1/2022 Page [40] of [147]

Location: DEANOS TRAVEL PLAZA 14

5055 N Reserve St

Missoula, MT 59808-1401 Missoula

System Facility ID:32-03610

Facility Code: 25301 Last Inspected On: 10/24/2022 Operating Permit Renewal Date: 12/21/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: DC Petroleum Inc 4067286052

 Operator Contact:
 Dean Clinkenbeard; Sheri Taylor
 4065438885

Owner/Operator: DC Petroleum Inc

Dean Clinkenbeard, UST Class A Operator Dean Clinkenbeard, UST Class B Global Operator

Sheri Taylor, UST Class A Operator Sheri Taylor, UST Class B Operator

Tank Code	06	Tank Age	31	Tank Installed Date	04/02/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	795	Spill Test Date	10/24/2022	Piping Installed Date	06/22/2007	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date	10/24/2022	Tank/Piping CP Test Date	10/24/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	10/24/2022	Line Tightness Test Date	07/22/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/24/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	07	Tank Age	31	Tank Installed Date	04/02/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	796	Spill Test Date	10/24/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	10/24/2022	Tank/Piping CP Test Date	10/24/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	10/24/2022	Line Tightness Test Date	07/23/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [41] of [147]

		Overfill Test Date	10/24/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	08	Tank Age	31	Tank Installed Date	04/02/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	797	Spill Test Date	10/24/2022	Piping Installed Date	06/22/2007	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	10/24/2022	Tank/Piping CP Test Date	10/24/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	10/24/2022	Line Tightness Test Date	07/23/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/24/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	09	Tank Age	31	Tank Installed Date	04/02/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	798	Spill Test Date	10/24/2022	Piping Installed Date	06/22/2007	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	10/24/2022	Tank/Piping CP Test Date	10/24/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	10/24/2022	Line Tightness Test Date	07/25/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/24/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	10	Tank Age	31	Tank Installed Date	04/02/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	799	Spill Test Date	10/24/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	10/24/2022	Tank/Piping CP Test Date	10/24/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	10/24/2022	Line Tightness Test Date	08/22/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [42] of [147]

# Overfill Test Date 10/24/2022 ATG Type Gilbarco-Veeder Root/TLS350/Gilbarco EMC; Veeder Root/8484 Series PLLD

#### Facility Summary in Missoula County in the City of Missoula

System Facility ID:60-15010

Location: DEANOS TRAVEL PLAZA II

5318 W Harrier

Missoula, MT 59801 Missoula

Facility Code: 30800

Last Inspected On: 04/23/2021 Operating Permit Renewal Date: 04/27/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: DC Petroleum Inc 4067286052

Operator Contact: Dean Clinkenbeard; Sheri Taylor 4065438885

Owner/Operator: DC Petroleum Inc

Dean Clinkenbeard, UST Class A Operator Dean Clinkenbeard, UST Class B Global Operator

Sheri Taylor, UST Class A Operator Sheri Taylor, UST Class B Operator

Tank Code	01	Tank Age	16	Tank Installed Date	01/17/2006	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5027	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date	09/10/2017	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/TLS-350				
Tank Code	02	Tank Age	16	Tank Installed Date	01/17/2006	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5028	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No

Report Created: 11/1/2022 Page [43] of [147]

Capacity	12000	ATG Test Date		Line Tightness Test Date	02/07/2018	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/TLS-350				
Tank Code	03	Tank Age	16	Tank Installed Date	01/17/2006	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5029	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	02/07/2018	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/TLS-350				

Location: DECKER TRUCK LINE INC

8350 Old Hwy 10

Missoula, MT 59808 Missoula

Facility Code: 30948
Last Inspected On: 06/25/2020
Operating Permit Renewal Date: 09/01/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Decker Truck Line Inc 5155744338

Operator Contact: Liam Lederer 4062747987

Owner/Operator: Decker Truck Line Inc

Cory Jelletich, UST Class B Global Operator Liam Lederer, UST Class A Operator Liam Lederer, UST Class B Global Operator

Tank Code	01	Tank Age	8	Tank Installed Date	03/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5438	Spill Test Date	11/16/2021	Piping Installed Date	08/30/2013	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/12/2020	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	11/16/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	20000	ATG Test Date	11/16/2021	Line Tightness Test Date		Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes

Report Created: 11/1/2022 Page [44] of [147]

		Overfill Test Date	11/16/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	8	Tank Installed Date	03/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5439	Spill Test Date		Piping Installed Date	08/25/2013	Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Other	MLLD Test Date		Sump Tightness Test Date	10/09/2013	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	DEF (Not Regulated)	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.1;Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.1;ELLD 0.2	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Not Listed	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Report Created: 11/1/2022 Page [45] of [147]

Location: DEMAROIS, INC

3115 W Broadway St

Missoula, MT 59808-1613 Missoula

System Facility ID:32-10552

Facility Code: 25588 Last Inspected On: 10/26/2021 Operating Permit Renewal Date: 01/08/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: DeMarois Inc

Operator Contact: Jack DeMarois

4067214000

Owner/Operator: DeMarois Inc

Jack DeMarois, UST Class A Operator Jack DeMarois, UST Class B Operator

Tank Code	03	Tank Age	24	Tank Installed Date	11/01/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	2188	Spill Test Date	10/26/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date	04/11/2022	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/11/2022			ATG Type	Gilbarco-Veeder Root/TLS-300				

# Facility Summary in Missoula County in the City of Missoula

Location: FAST TRIP CONOCO

2730 S Reserve St

Missoula, MT 59801-7641 Missoula

Facility Code: 30584 Last Inspected On: 03/22/2022

System Facility ID:56-13914 Operating Permit Renewal Date: 07/02/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Scott Worster

Operator Contact: Deb Privett 4065297771

Owner/Operator: Scott Worster

Page [46] of [147] Report Created: 11/1/2022

#### Deb Privett, UST Class A Operator Deb Privett, UST Class B Operator

Tank Code	01	Tank Age	23	Tank Installed Date	08/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4913	Spill Test Date	06/07/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	l	Sump Tightness Test Date	06/03/2020	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	03/22/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	15000	ATG Test Date	03/22/2022	Line Tightness Test Date	12/02/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	02	Tank Age	23	Tank Installed Date	08/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4914	Spill Test Date	06/07/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/03/2020	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	03/22/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date	03/22/2022	Line Tightness Test Date	11/14/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	23	Tank Installed Date	08/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4915	Spill Test Date	06/07/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/03/2020	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	03/22/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date	03/22/2022	Line Tightness Test Date	10/25/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [47] of [147]

# Overfill Test Date ATG Type Gilbarco-Veeder Root/TLS350/Gilbarco EMC;Veeder Root/8484 Series PLLD

#### Facility Summary in Missoula County in the City of Missoula

Location: FINEST OIL CO MISSOULA NORTHGATE

3665 Grant Creek Rd

Missoula, MT 59808-1431 Missoula

Facility Code: 25257

Last Inspected On: 04/21/2020

System Facility ID:32-02295 Operating Permit Renewal Date: 08/09/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Finest Oil Co 4065436969

Operator Contact: Christopher Glasser; David Peyton; James Brady; James

DeWaters; Justin Gaudot; Stephen Hanson

4062181563;4063606327;4065436969;4065441005;7143338926

Owner/Operator: Finest Oil Co

Christopher Glasser, UST Class A Operator

David Peyton, UST Class A Operator

David Peyton, UST Class B Global Operator

James Brady, UST Class A Operator

James DeWaters, UST Class A Operator

Joseph McClain, UST Class B Operator

Justin Gaudot, UST Class A Operator

Justin Gaudot, UST Class B Global Operator

Stephen Hanson, UST Class A Operator

Stephen Hanson, UST Class B Operator

Tank Code	06	Tank Age	31	Tank Installed Date	07/01/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1066	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	07	Tank Age	31	Tank Installed Date	07/01/1991	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Report Created: 11/1/2022 Page [48] of [147]

Tag Number	1067	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	08	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Γag Number	1068	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Γank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	09	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1069	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	10	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Гад Number	1070	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Γank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Report Created: 11/1/2022 Page [49] of [147]

Tank Code	11	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1071	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	12	Tank Age	28	Tank Installed Date	05/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1072	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	13	Tank Age	28	Tank Installed Date	05/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1073	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/21/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Location: FINEST OIL EASTGATE

940 E Broadway St Missoula, MT 59802-4915 Missoula

Facility Code: 25565
Last Inspected On: 05/04/2022
Operating Permit Renewal Date: 09/17/2025 System Facility ID:32-10284

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Page [50] of [147] Report Created: 11/1/2022

**Operator Contact:** Christopher Glasser;David Peyton;James Brady;James DeWaters;Justin Gaudot;Stephen Hanson

4062181563;4063606327;4065436969;4065441005;7143338926

Owner/Operator: Finest Oil Co

Christopher Glasser, UST Class A Operator
David Peyton, UST Class A Operator
David Peyton, UST Class B Global Operator
James Brady, UST Class A Operator
James DeWaters, UST Class A Operator
John Stordahl, UST Class B Global Operator
Joseph McClain, UST Class B Operator
Justin Gaudot, UST Class A Operator
Justin Gaudot, UST Class B Global Operator
Stephen Hanson, UST Class A Operator
Stephen Hanson, UST Class B Operator

Tank Code	07	Tank Age	25	Tank Installed Date	10/27/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	1074	Spill Test Date	05/04/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/04/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	15000	ATG Test Date	05/04/2022	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/04/2022			ATG Type	Gilbarco/EMC Basic				
Tank Code	00										
Talik Code	08	Tank Age	25	Tank Installed Date	10/27/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	1075	Tank Age Spill Test Date	25  05/04/2022		10/27/1997	Tank Material Tank Construction		Piping Material Piping Construction	Flexible Plastic  Double Walled	Overfill Types AST	High Level Alarm  No
				Date Piping Installed	10/27/1997	Tank		Piping			
Tag Number	1075	Spill Test Date		Date Piping Installed Date Sump Tightness	10/27/1997	Tank Construction Catastrophic L.D	Reinforced Plastic	Piping Construction	Double Walled	AST	No
Tag Number Tank Status	1075 Currently in Use	Spill Test Date  MLLD Test Date	05/04/2022	Date Piping Installed Date Sump Tightness Test Date Tank/Piping CP	10/27/1997	Tank Construction Catastrophic L.D Type 3.0 Primary Tank	Reinforced Plastic  Electronic Line Leak Detector  Automatic Tank	Piping Construction Piping Type Primary Pipe	Double Walled Pressurized	AST  CP Met Types	No Non-corrodible

Report Created: 11/1/2022 Page [51] of [147]

Tank Code	09	Tank Age	25	Tank Installed Date	10/27/1997		Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	1076	Spill Test Date	05/04/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/04/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date	05/04/2022	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/04/2022			ATG Type	Gilbarco/EMC Basic				

Location: GARYS CONOCO SERVICE

2125 S Higgins Ave Missoula, MT 59801-6760 Missoula

Facility Code: 25541 Last Inspected On: 12/02/2020

System Facility ID:32-10053 Operating Permit Renewal Date: 01/22/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Gary Little 4065420121

Operator Contact: Timothy Little 4065420121

Owner/Operator: Gary D Little

Timothy Little, UST Class A Operator Timothy Little, UST Class B Operator

	•	,									
Tank Code	08	Tank Age	32	Tank Installed Date	09/30/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2139	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	12/02/2020	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date	12/02/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-300				
Tank Code	09	Tank Age	32	Tank Installed Date	09/30/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Page [52] of [147] Report Created: 11/1/2022

Tag Number	2140	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	12/02/2020	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	12/02/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-300				
Tank Code	10	Tank Age	32	Tank Installed Date	09/30/1990	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2141	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	3000	ATG Test Date		Line Tightness Test Date	10/15/2018	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-300				

Location: GREAT WESTERN PETROLEUM

1002 E Broadway St

Missoula, MT 59802-4930 Missoula

Facility Code: 25437

Last Inspected On: 10/21/2021
Operating Permit Renewal Date: 10/30/2024

System Facility ID:32-07431

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Tabish Brothers Distributors Inc 4065437621

Operator Contact: Heather Stiles

Owner/Operator: Tabish Brothers Distributors Inc

Heather Stiles, UST Class A Operator Heather Stiles, UST Class B Global Operator

Tank Code	10	Tank Age	24	Tank Installed Date	06/01/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1432	Spill Test Date	10/07/2021	Piping Installed Date	08/26/2006	Tank Construction		Piping Construction	Double Walled	AST	No

Report Created: 11/1/2022 Page [53] of [147]

Tank Status	Currently in Use	MLLD Test Date	10/21/2021	Sump Tightness Test Date	07/27/2018	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	5000	ATG Test Date	10/07/2021	Line Tightness Test Date	10/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	10/07/2021			ATG Type	Gilbarco/EMC Basic;Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	S11	Tank Age	24	Tank Installed Date	06/01/1998	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	1433	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/21/2021	Sump Tightness Test Date	07/27/2018	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	17000	ATG Test Date	10/07/2021	Line Tightness Test Date	10/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000;Veeder Root/Vaporless 99LD-2000				
Tank Code	S12	Tank Age	24	Tank Installed Date	06/01/1998	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	1434	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/21/2021	Sump Tightness Test Date	07/27/2018	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	11000	ATG Test Date	10/07/2021	Line Tightness Test Date	10/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [54] of [147]

		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	S13	Tank Age	24	Tank Installed Date	06/01/1998	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	
Tag Number	1435	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/21/2021	Sump Tightness Test Date	07/27/2018	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	14600	ATG Test Date	10/07/2021	Line Tightness Test Date	10/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	S14	Tank Age	24	Tank Installed Date	06/01/1998	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	
Гад Number	1436	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/21/2021	Sump Tightness Test Date	07/27/2018	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	11000	ATG Test Date	10/07/2021	Line Tightness Test Date	10/21/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				

Location: HEATING PLANT

Physical Plant Bldg #32 Missoula, MT 59812 Missoula

System Facility ID:32-00505

Facility Code: 25184 Last Inspected On: 11/08/2019 Operating Permit Renewal Date: 02/22/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Page [55] of [147] Report Created: 11/1/2022

Owner Operator Contact: University of Montana 4062432190

Operator Contact: Michael Burke; Neil Maier 4062432190; 4065466013

Owner/Operator: University of Montana

Michael Burke, UST Class A Operator Michael Burke, UST Class B Operator Neil Maier, UST Class A Operator Neil Maier, UST Class B Operator

Tank Code	09	Tank Age	24	Tank Installed Date	11/01/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4221	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/05/2019	Catastrophic L.D Type 3.0	Not Required	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Automatic Tank Gauging 0.1	Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 300;Veeder Root/TLS-300				

# Facility Summary in Missoula County in the City of Missoula

Location: HELLGATE CONOCO SERVICE CENTER

711 E Broadway St

Missoula, MT 59802-4609 Missoula

Facility Code: 25156

Last Inspected On: 04/20/2020 System Facility ID:32-00144 Operating Permit Renewal Date: 06/14/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Hellgate Conoco Service Center;Ross Grenfell 4067289966

Operator Contact: Ross Grenfell 4067289966

Owner/Operator: Hellgate Conoco Service Center

Owner/Operator: Ross Grenfell

Ross Grenfell, UST Class A Operator

Report Created: 11/1/2022 Page [56] of [147]

#### Ross Grenfell, UST Class B Global Operator

Tank Code	01	Tank Age	56	Tank Installed Date	03/31/1966	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3765	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	10/28/2015	Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/20/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	56	Tank Installed Date	03/31/1966	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3766	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	09/25/2019	Sump Tightness Test Date	10/28/2015	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/20/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	09/25/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	03	Tank Age	56	Tank Installed Date	03/31/1966	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3767	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	09/25/2019	Sump Tightness Test Date	10/28/2015	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/20/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	09/25/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [57] of [147]

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Vaporless Manufacturing/Va porless LD-2000				
Tank Code	08	Tank Age	12	Tank Installed Date	12/16/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	5279	Spill Test Date		Piping Installed Date	12/16/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	09/25/2019	Sump Tightness Test Date	10/28/2015	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/15/2017	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	8000	ATG Test Date		Line Tightness Test Date	09/25/2019	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC;Vaporless Manufacturing/Va porless LD-2000				

Location: HELLGATE TRADING POST INC

6265 Mullan Rd

Missoula, MT 59808-5650 Missoula

System Facility ID:32-00211

Facility Code: 25173
Last Inspected On: 04/29/2022
Operating Permit Renewal Date: 06/03/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Tabish Brothers Distributors Inc 4065437621

Operator Contact: Karly Shafer;Malinda Davis 4063962206;4067288644

Owner/Operator: Tabish Brothers Distributors Inc

Heather Stiles, UST Class B Global Operator

Karly Shafer, UST Class A Operator

Karly Shafer, UST Class B Global Operator Malinda Davis, UST Class A Operator

Malinda Davis, UST Class B Global Operator

Tank Code 03 Tank Age 28 Tank Installed Date 09/01/1994 Tank Material Fiberglass Reinforced Plastic Piping Material Fiberglass Reinforced Piping Mater

Report Created: 11/1/2022 Page [58] of [147]

Tag Number	1425	Spill Test Date	04/24/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	02/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	04/29/2022	Line Tightness Test Date	02/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/24/2022			ATG Type	Gilbarco/EMC Basic				
Tank Code	04	Tank Age	28	Tank Installed Date	09/01/1994	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1426	Spill Test Date	04/24/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	02/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	02/18/2022	Line Tightness Test Date	02/18/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	04/24/2022			ATG Type	Gilbarco/EMC Basic				

Location: JAYS 1 STOP

505 Highton St

Missoula, MT 59801-5424 Missoula

Facility Code: 25412 Last Inspected On: 04/07/2020

System Facility ID:32-06680 Operating Permit Renewal Date: 07/31/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Jays Corporation

Operator Contact: Ashish Patel;Jayprakash Patel 6509968294

Owner/Operator: Jays Corporation

Ashish Patel, UST Class A Operator Ashish Patel, UST Class B Operator Jayprakash Patel, UST Class A Operator Jayprakash Patel, UST Class B Operator

Tank Code	03	Tank Age	32	Tank Installed Date	01/10/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
-----------	----	----------	----	---------------------	------------	---------------	---------------------------------	-----------------	------------------	----------------	------------------

Report Created: 11/1/2022 Page [59] of [147]

Tag Number	2298	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/27/2020	Sump Tightness Test Date	03/27/2020	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/27/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	07/24/2017	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	04	Tank Age	32	Tank Installed Date	01/10/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2299	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/27/2020	Sump Tightness Test Date	03/27/2020	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/27/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	07/24/2017	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	05	Tank Age	32	Tank Installed Date	01/10/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2300	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/27/2020	Sump Tightness Test Date	03/27/2020	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/27/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	07/24/2017	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Location: JAYS FOOD STORE 2738 W Broadway St Missoula, MT 59808-1622 Missoula

Facility Code: 25377
Last Inspected On: 02/20/2020
Operating Permit Renewal Date: 08/02/2023 System Facility ID:32-05760

Page [60] of [147] Report Created: 11/1/2022

Owner Operator Contact: Jays Corporation

Operator Contact: Jagpreet Ghuman; Jaspal Sandhu

4068807677

# Owner/Operator: Jays Corporation

Jagpreet Ghuman, UST Class A Operator
Jagpreet Ghuman, UST Class B Global Operator
Jaspal Sandhu, UST Class A Operator
Jaspal Sandhu, UST Class B Global Operator
Jaspal Sandhu, UST Class B Operator

Tank Code	01	Tank Age	50	Tank Installed Date	11/18/1972	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1345	Spill Test Date		Piping Installed Date	10/10/2015	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	10/10/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	12/03/2019	Tank/Piping CP Test Date	07/31/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	10/12/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	02	Tank Age	46	Tank Installed Date	11/18/1976	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1346	Spill Test Date		Piping Installed Date	10/10/2015	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	10/10/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	12/03/2019	Tank/Piping CP Test Date	07/31/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	10/14/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No

Report Created: 11/1/2022 Page [61] of [147]

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	50	Tank Installed Date	11/18/1972	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1347	Spill Test Date		Piping Installed Date	10/10/2015	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	10/10/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	12/03/2019	Tank/Piping CP Test Date	07/31/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	10/14/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				

System Facility ID:32-05761

Location: JAYS FOOD STORE CARDLOCK

2738 W Broadway St

Missoula, MT 59808-1622 Missoula

Facility Code: 25378 Last Inspected On: 07/15/2022

Operating Permit Renewal Date: 07/15/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Jays Corporation

Operator Contact: Jagpreet Ghuman 4068807677

Owner/Operator: Jays Corporation

Jagpreet Ghuman, UST Class A Operator Jagpreet Ghuman, UST Class B Global Operator Jaspal Sandhu, UST Class B Global Operator

Tank Code	01	Tank Age	43	Tank Installed Date	11/14/1979	Tank Material	Bare Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	3627	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No

Report Created: 11/1/2022 Page [62] of [147]

Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/28/2022	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	02	Tank Age	47	Tank Installed Date	11/14/1975	Tank Material	Bare Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	3628	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date	06/28/2022	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	03	Tank Age	43	Tank Installed Date	11/14/1979	Tank Material	Bare Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	3629	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/28/2022	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

Location: JAYS MART INC

2480 39th St

Missoula, MT 59803-1123 Missoula

Facility Code: 25511
Last Inspected On: 02/20/2020
Operating Permit Renewal Date: 08/02/2023 System Facility ID:32-09690

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Hi-Star Properties LLC

Page [63] of [147] Report Created: 11/1/2022

# Owner/Operator: Hi-Star Properties LLC

Jagpreet Ghuman, UST Class A Operator
Jagpreet Ghuman, UST Class B Global Operator
Jaspal Sandhu, UST Class B Global Operator
Manpreet Singh, UST Class A Operator
Manpreet Singh, UST Class B Global Operator
Manpreet Singh, UST Class B Operator

Tank Code	01	Tank Age	40	Tank Installed Date	11/03/1982	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1360	Spill Test Date		Piping Installed Date	04/27/2018	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	12/03/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8494 Series WPLLD				
Tank Code	02	Tank Age	40	Tank Installed Date	11/03/1982	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1361	Spill Test Date		Piping Installed Date	04/27/2018	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	12/03/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8494 Series WPLLD				
Tank Code	03	Tank Age	40	Tank Installed Date	11/03/1982	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve

Report Created: 11/1/2022 Page [64] of [147]

Tag Number	1362	Spill Test Date	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	Sump Tightness Test Date	04/27/2018	Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	Tank/Piping CP Test Date	12/03/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	Yes
Capacity	6000	ATG Test Date	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Location: KARL TYLER CHEVROLET INC N RESERVE

3663 N Reserve St

Missoula, MT 59808-1509 Missoula

System Facility ID:56-14056

Facility Code: 30710 Last Inspected On: 08/10/2020 Operating Permit Renewal Date: 09/10/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Karl Tyler Chevrolet Inc

Operator Contact: Terry Hedrick

Owner/Operator: Karl Tyler Chevrolet Inc

Terry Hedrick, UST Class A Operator Terry Hedrick, UST Class B Operator

Tank Code	02	Tank Age	20	Tank Installed Date	07/22/2002	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4695	Spill Test Date	09/24/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	09/20/2020	Sump Tightness Test Date	08/10/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date	09/24/2021	Line Tightness Test Date	09/20/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [65] of [147]

		Overfill Test Date	09/24/2021			ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000;Veeder Root/TLS-300				
Tank Code	03	Tank Age	20	Tank Installed Date	07/22/2002	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4696	Spill Test Date	09/24/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	09/20/2020	Sump Tightness Test Date	08/10/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date	09/24/2021	Line Tightness Test Date	09/20/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	09/24/2021			ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000;Veeder Root/TLS-300				
Tank Code	S1	Tank Age	20	Tank Installed Date	07/30/2002	Tank Material	Aboveground Tank	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4699	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	08/10/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Pressurized	CP Met Types	
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date	09/24/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					T

Location: LOVES TRAVEL STOP #753

8077 Hwy 10 W Missoula, MT 59808 Missoula

Facility Code: 31018
Last Inspected On: 01/20/2022
Operating Permit Renewal Date: 01/28/2025

System Facility ID:60-15321

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Loves Travel Stops and Country Stores Inc

Page [66] of [147] Report Created: 11/1/2022

# Owner/Operator: Loves Travel Stops and Country Stores Inc

Ted Lowery, UST Class A Operator Ted Lowery, UST Class B Operator Zach Moore, UST Class A Operator Zach Moore, UST Class B Global Operator

Tank Code	01	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5830	Spill Test Date	11/15/2018	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	02	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5831	Spill Test Date	11/15/2018	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	03	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5832	Spill Test Date	11/15/2018	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Report Created: 11/1/2022 Page [67] of [147]

Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	04	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5833	Spill Test Date	04/26/2022	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	04/26/2022			ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	05	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5834	Spill Test Date	11/15/2018	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	06	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5835	Spill Test Date	11/15/2018	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	07	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5836	Spill Test Date	11/15/2018	Piping Installed Date	08/15/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/15/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Biodiesel, <=B20	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	08	Tank Age	3	Tank Installed Date	08/15/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	
Tag Number	5837	Spill Test Date		Piping Installed Date	08/15/2019	Tank Construction		Piping Construction		AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0		Piping Type	Pressurized	CP Met Types	
Product	DEF (Not Regulated)	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Not Listed	Primary Pipe Detection	Not Listed	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Not Listed	Energy Act	Yes
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	09	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5863	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Motor	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	2000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes

		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				
Tank Code	10	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5864	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Motor	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				
Tank Code	11	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5865	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Motor	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	2000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				
Tank Code	12	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5866	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Motor	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				
Tank Code	13	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5867	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No

Report Created: 11/1/2022 Page [70] of [147]

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Motor	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	2000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				
Tank Code	14	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5868	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	7000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				
Tank Code	15	Tank Age	4	Tank Installed Date	10/26/2018	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5869	Spill Test Date	11/24/2020	Piping Installed Date	12/17/2019	Tank Construction		Piping Construction	Secondary Containment Chase	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/24/2020	Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Oil, Motor	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	2000	ATG Test Date	11/24/2020	Line Tightness Test Date	11/24/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date	11/24/2020			ATG Type	Incon/TS-550 EVO				

Location: MDOT MISSOULA 2100 W Broadway St Missoula, MT 59808-1816 Missoula

Facility Code: 25486 Last Inspected On: 06/22/2021 Operating Permit Renewal Date: 07/10/2024

System Facility ID:32-09304

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: MDOT Helena 4064446163

Page [71] of [147] Report Created: 11/1/2022

Operator Contact: Jeff Gleason; Joe Radonich; Michael Carstensen; Mike Murolo; Walt Kerttula

4064447647

Owner/Operator: MDOT Helena

Chad Pearson, UST Class B Operator
Jeff Gleason, UST Class A Operator
Joe Radonich, UST Class A Operator
Joe Radonich, UST Class B Global Operator
John Maricelli, UST Class B Operator
Justin Marin, UST Class B Operator
Michael Carstensen, UST Class A Operator
Michael Carstensen, UST Class B Operator
Mike Murolo, UST Class A Operator
Richard Bick, UST Class B Operator
Walt Kerttula, UST Class A Operator

Tank Code	01	Tank Age	38	Tank Installed Date	05/01/1984	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2917	Spill Test Date	06/22/2021	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	05/19/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date	06/22/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	09/30/2021			ATG Type	Gilbarco/EMC Basic				
Tank Code	06	Tank Age	35	Tank Installed Date	04/01/1987	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2918	Spill Test Date	06/22/2021	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	05/19/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date	06/22/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	09/30/2021			ATG Type	Gilbarco/EMC Basic				

Facility Summary in Missoula County in the City of Missoula

Report Created: 11/1/2022 Page [72] of [147]

Location: MISSOULA #7 FLYING J

8745 Hwy 93 N Missoula, MT 59808 Missoula

System Facility ID:60-15158

Facility Code: 30899 Last Inspected On: 09/09/2021 Operating Permit Renewal Date: 02/21/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Missoula 7 Town Pump LLC 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Missoula 7 Town Pump LLC

Trent Biggers, UST Class A Operator Trent Biggers, UST Class B Global Operator

Tank Code	01	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5256	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	02	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5257	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	03	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Page [73] of [147] Report Created: 11/1/2022

Tag Number	5258	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	25000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	04	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5259	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	30000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	05	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5260	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	06	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5261	Spill Test Date	07/13/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Report Created: 11/1/2022 Page [74] of [147]

Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	15000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	07	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5262	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	08	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5331	Spill Test Date	09/09/2021	Piping Installed Date	07/19/2010	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date	09/09/2021			ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	09	Tank Age	12	Tank Installed Date	09/01/2010	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	5361	Spill Test Date		Piping Installed Date	04/11/2012	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Other	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Not Listed	CP Met Types	
Product	DEF (Not Regulated)	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Approved Remote Monitoring;Contin uous Interstitial Monitoring	Primary Pipe Detection	Approved Remote Monitoring;Continu ous Interstitial Monitoring	Vapor Recovery	No

Report Created: 11/1/2022 Page [75] of [147]

Capacity	10000	ATG Test Date	Line Tightness Test Date	Secondary Tank Leak Detection	Secondary Pipe Detection	Energy Act Yes
		Overfill Test Date		ATG Type		

Location: MISSOULA AIRPORT WASHINGTON HANGER

5225 W Broadway St

Missoula, MT 59808-9385 Missoula

System Facility ID:32-07606

Facility Code: 25444
Last Inspected On: 02/26/2020
Operating Permit Renewal Date: 05/25/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Washington Corporations 4065231349

Operator Contact: Gabriel Martinez;Roy Felt;Ryan Opheim 4062148531;4065231427

Owner/Operator: Washington Corporations

Gabriel Martinez, UST Class A Operator Gabriel Martinez, UST Class B Operator

Roy Felt, UST Class A Operator

Roy Felt, UST Class B Global Operator Ryan Opheim, UST Class A Operator Ryan Opheim, UST Class B Operator

Tank Code	01	Tank Age	38	Tank Installed Date	05/07/1984	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	2242	Spill Test Date	03/21/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/21/2022	Sump Tightness Test Date	03/21/2022	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Jet Fuel (Jet- A, Jet-A1, JP5)	PLLD Test Date		Tank/Piping CP Test Date	02/26/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date	03/21/2022	Line Tightness Test Date	02/26/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	03/21/2022			ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000;Veeder Root/TLS-300				

Facility Summary in Missoula County in the City of Missoula

Report Created: 11/1/2022 Page [76] of [147]

Location: MISSOULA COUNTY DETENTION CENTER

2340 Mullan Rd

Missoula, MT 59808-1830 Missoula

System Facility ID:56-13921

Facility Code: 30591
Last Inspected On: 11/10/2021
Operating Permit Renewal Date: 11/16/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Missoula County Detention Center 4068294000

Operator Contact: Gary Zinke; Jess Ebel 4065313627

Owner/Operator: Missoula County Detention Center

Gary Zinke, UST Class A Operator Gary Zinke, UST Class B Operator Jess Ebel, UST Class A Operator Jess Ebel, UST Class B Operator

Tank Code	S1	Tank Age	23	Tank Installed Date	06/01/1999	Tank Material	Unknown	Piping Material	Copper	Overfill Types	
Tag Number	3774	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Secondary Containment Chase	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	11/10/2021	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	3000	ATG Test Date	11/10/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

#### Facility Summary in Missoula County in the City of Missoula

System Facility ID:32-01182

Location: MISSOULA SERVICE CENTER

1900 S Russell St

Missoula, MT 59801-6624 Missoula

Facility Code: 25203 Last Inspected On: 01/08/2020

Operating Permit Renewal Date: 06/13/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Northwestern Energy Butte 4066552521

Report Created: 11/1/2022 Page [77] of [147]

Operator Contact: Brian Ranf; John Habeger

Owner/Operator: Northwestern Energy Butte

Brian Ranf, UST Class A Operator
Bruce Schlichenmayer, UST Class B Operator
Greg Sponseller, UST Class B Operator
Joe Vigue, UST Class B Operator
John Habeger, UST Class A Operator

Tank Code	04	Tank Age	32	Tank Installed Date	07/27/1990	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1680	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	12/06/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	13000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-300				
Tank Code	05	Tank Age	32	Tank Installed Date	07/27/1990	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1681	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	12/06/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	3000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-300				

## Facility Summary in Missoula County in the City of Missoula

Location: MISSOULA TRAVEL CENTER

8018 US Hwy 93 N

Missoula, MT 59808 Missoula

Facility Code: 25272
Last Inspected On: 08/21/2020
Operating Permit Renewal Date: 10/31/2023

System Facility ID:32-02822 Operating Permit Renewal Date: 10/31/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Report Created: 11/1/2022 Page [78] of [147]

Operator Contact: Alex Hoskinson; Greg Goodwin; Jack Odyk; Joshua

4058331186;4065492327;4408087406;5092172694

Johnson; Kelly Gelske; Kimberly Komar; Lisa Hendon; Tracy

Mullins

# Owner/Operator: TA Operating LLC

Alex Hoskinson, UST Class A Operator Alex Hoskinson, UST Class B Operator Greg Goodwin, UST Class A Operator Greg Goodwin, UST Class B Global Operator Jack Odyk, UST Class A Operator

Jack Odyk, UST Class B Global Operator

Jack Odyk, UST Class B Operator

Joshua Johnson, UST Class A Operator

Joshua Johnson, UST Class B Global Operator

Joshua Johnson, UST Class B Operator

Kelly Gelske, UST Class A Operator

Kelly Gelske, UST Class B Global Operator

Kimberly Komar, UST Class A Operator

Kimberly Komar, UST Class B Global Operator

Lisa Hendon, UST Class A Operator

Lisa Hendon, UST Class B Global Operator

Tracy Mullins, UST Class A Operator

Tracy Mullins, UST Class B Global Operator

Tank Code	13	Tank Age	8	Tank Installed Date	08/22/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5511	Spill Test Date		Piping Installed Date	07/29/2014	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Other	MLLD Test Date		Sump Tightness Test Date	08/18/2014	Catastrophic L.D Type 3.0		Piping Type	Pressurized	CP Met Types	
Product	DEF (Not Regulated)	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Not Listed	Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS- 300				
Tank Code	14	Tank Age	7	Tank Installed Date	02/24/2015	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	5550	Spill Test Date		Piping Installed Date	09/18/2014	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No

Report Created: 11/1/2022 Page [79] of [147]

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Oil Substance	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	03/12/2015	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	15	Tank Age	7	Tank Installed Date	02/24/2015	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	5551	Spill Test Date		Piping Installed Date	09/18/2014	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Gravity Feed	CP Met Types	Non-corrodible
Product	Oil Substance	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	03/12/2015	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	16	Tank Age	3	Tank Installed Date	07/31/2019	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve;High Leve Alarm
Tag Number	5929	Spill Test Date		Piping Installed Date	07/31/2019	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	04/30/2020	Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/30/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	MLLD Line Tightness Testing	Energy Act	Yes
		Overfill Test Date				ATG Type	Franklin Fueling Systems/FE Petro STP-MLD +D;Gilbarco- Veeder Root/TLS- 350				
Tank Code	02	Tank Age	44	Tank Installed Date	02/17/1978	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	786	Spill Test Date		Piping Installed Date	08/22/2014	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No

Report Created: 11/1/2022 Page [80] of [147]

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	05/16/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	07/18/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	03	Tank Age	44	Tank Installed Date	02/17/1978	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	787	Spill Test Date		Piping Installed Date	08/22/2014	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	05/19/2021	Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	05/16/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	05/19/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	09	Tank Age	29	Tank Installed Date	11/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	788	Spill Test Date		Piping Installed Date	06/10/2010	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	04/30/2020	Tank/Piping CP Test Date	05/16/2020	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	04/30/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	10	Tank Age	29	Tank Installed Date	11/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	789	Spill Test Date		Piping Installed Date	08/22/2014	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/30/2020	Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	05/16/2020	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No

Report Created: 11/1/2022 Page [81] of [147]

Capacity	10000	ATG Test Date		Line Tightness Test Date	08/04/2014	Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	11	Tank Age	29	Tank Installed Date	11/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	790	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	08/18/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	04/30/2020	Tank/Piping CP Test Date	05/16/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/30/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	12	Tank Age	29	Tank Installed Date	11/01/1993	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	791	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	08/18/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date	04/30/2020	Tank/Piping CP Test Date	05/16/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	04/30/2020	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

**Location:** MISSOULA URBAN TRANSPORTATION 1221 Shakespeare St

Missoula, MT 59802-2307 Missoula

Facility Code: 25341 Last Inspected On: 04/02/2020 Operating Permit Renewal Date: 06/05/2023

System Facility ID:32-04427

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Missoula Urban Transportation

4062152455;4062152458 Operator Contact: Jeffrey Logan;John Roseboom

Page [82] of [147] Report Created: 11/1/2022

# Owner/Operator: Missoula Urban Transportation

Brian Dildine, UST Class B Operator
Cody Bush, UST Class B Operator
David Loewen, UST Class B Operator
Jacob Nolen, UST Class B Operator
Jeffrey Logan, UST Class A Operator
Jeffrey Logan, UST Class B Operator
John Roseboom, UST Class A Operator
John Roseboom, UST Class B Operator
Kent Russell, UST Class B Operator

Tank Code	04	Tank Age	24	Tank Installed Date	04/30/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;Flapper Valve
Tag Number	1658	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic;Gilbarco- Veeder Root/EMC Basic				
Tank Code	05	Tank Age	24	Tank Installed Date	04/30/1998	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	1659	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/07/2019	Catastrophic L.D Type 3.0	Not Required	Piping Type	Gravity Feed	CP Met Types	Non-corrodible
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	600	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Gilbarco- Veeder Root/EMC Basic				

Facility Summary in Missoula County in the City of Missoula

Report Created: 11/1/2022 Page [83] of [147]

Location: MONTANA RAIL LINK INC RAILYARD MISSOULA

101 International Dr

Missoula, MT 59808-1549 Missoula

System Facility ID:32-11226

Facility Code: 25626
Last Inspected On: 03/25/2021
Operating Permit Renewal Date: 03/27/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Montana Rail Link Inc Missoula 4065231500

Operator Contact: Richard Shelley 4062223764

Owner/Operator: Montana Rail Link Inc Missoula

Richard Shelley, UST Class A Operator Richard Shelley, UST Class B Operator

Tank Code	S5	Tank Age	32	Tank Installed Date	11/01/1990	Tank Material	Unknown	Piping Material	Steel	Overfill Types	
Tag Number	3872	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	12/01/2020	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	30000	ATG Test Date		Line Tightness Test Date	10/19/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

## Facility Summary in Missoula County in the City of Missoula

Location: MOUNTAIN WEST COOP

4570 N Reserve St

Missoula, MT 59808 Missoula

Facility Code: 25260 Last Inspected On: 04/01/2021

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: CHS Inc Inver Grove Heights 8002323639

Operator Contact: Bob Westin; Dusty Smith; John Thompson; Robin McCurdy; Will 4065464885; 4066651728; 4067577427; 4068808169

Dukart

Owner/Operator: CHS Inc Inver Grove Heights

Bill Griffin, UST Class B Operator Bob Westin, UST Class A Operator

Report Created: 11/1/2022 Page [84] of [147]

Bob Westin, UST Class B Global Operator
Dusty Smith, UST Class A Operator
Dusty Smith, UST Class B Global Operator
John Thompson, UST Class B Global Operator
John Thompson, UST Class B Global Operator
John Thompson, UST Class B Operator
Mike Dunlon, UST Class B Operator
Robin McCurdy, UST Class A Operator
Robin McCurdy, UST Class B Operator
Will Dukart, UST Class A Operator

Tank Code	16	Tank Age	27	Tank Installed Date	03/29/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	2859	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	03/31/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	06/12/2014	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	17	Tank Age	8	Tank Installed Date	11/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5554	Spill Test Date		Piping Installed Date	01/16/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/11/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	25000	ATG Test Date		Line Tightness Test Date	01/16/2015	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	18	Tank Age	8	Tank Installed Date	11/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5555	Spill Test Date		Piping Installed Date	01/16/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No

Report Created: 11/1/2022 Page [85] of [147]

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/11/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	25000	ATG Test Date		Line Tightness Test Date	01/16/2015	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	19	Tank Age	8	Tank Installed Date	11/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarn
Tag Number	5556	Spill Test Date		Piping Installed Date	01/16/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/11/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/16/2015	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	20	Tank Age	8	Tank Installed Date	11/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5557	Spill Test Date		Piping Installed Date	01/16/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/11/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	01/16/2015	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	21	Tank Age	8	Tank Installed Date	11/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5558	Spill Test Date		Piping Installed Date	01/16/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/11/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/16/2015	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	22	Tank Age	8	Tank Installed Date	11/01/2014	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5559	Spill Test Date		Piping Installed Date	01/16/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	12/11/2014	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	10000	ATG Test Date		Line Tightness Test Date	09/16/2022	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				

Location: MURALTS TRUCK PLAZA

8800 Truck Stop Rd

Missoula, MT 59808-9708 Missoula

Facility Code: 25157 Last Inspected On: 01/14/2021

System Facility ID:32-00146 Operating Permit Renewal Date: 01/14/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Muralts Inc 4067284700

Operator Contact: Curtis Wilson 4062075448

Owner/Operator: Muralts Inc

Curtis Wilson, UST Class A Operator Curtis Wilson, UST Class B Operator J Kelley, UST Class B Global Operator

Report Created: 11/1/2022 Page [87] of [147]

Tank Code	10	Tank Age	27	Tank Installed Date	11/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1734	Spill Test Date		Piping Installed Date	01/12/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	05/19/2009	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	11	Tank Age	27	Tank Installed Date	11/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1735	Spill Test Date		Piping Installed Date	01/12/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	05/19/2009	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	01	Tank Age	54	Tank Installed Date	03/26/1968	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3650	Spill Test Date		Piping Installed Date	01/12/2016	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	07/23/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				

Report Created: 11/1/2022 Page [88] of [147]

Tank Code	02	Tank Age	54	Tank Installed Date	03/26/1968	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3651	Spill Test Date		Piping Installed Date	01/12/2016	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	07/23/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	03	Tank Age	54	Tank Installed Date	03/26/1968	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3652	Spill Test Date		Piping Installed Date	01/12/2016	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	07/23/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	04	Tank Age	54	Tank Installed Date	03/26/1968	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	3653	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	07/23/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [89] of [147]

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	05	Tank Age	54	Tank Installed Date	03/26/1968	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	3654	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	07/23/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				
Tank Code	06	Tank Age	49	Tank Installed Date	03/26/1973	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	3655	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	12/17/2020	Tank/Piping CP Test Date	07/23/2018	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	01/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 450;Veeder Root/8590 Series DPLLD				

Location: NOONS 426 1250 39th St

Missoula, MT 59803 Missoula

System Facility ID:32-05763

Facility Code: 25380 Last Inspected On: 08/15/2022 Operating Permit Renewal Date: 12/10/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Hi Noon Petroleum Missoula

Page [90] of [147] Report Created: 11/1/2022

Baker

# Owner/Operator: Hi Noon Petroleum Missoula

Allisa Gilstrap, UST Class B Global Operator
Allisa Gilstrap, UST Class B Operator
Andrew Young, UST Class A Operator
Andrew Young, UST Class B Global Operator
Cameron Fulmer, UST Class B Global Operator
Earl Allen, UST Class A Operator
Earl Allen, UST Class B Global Operator
Erin Keffeler, UST Class B Global Operator
Erin Keffeler, UST Class B Global Operator
Holly Dale, UST Class B Global Operator
John Monahan, UST Class B Global Operator
John Monahan, UST Class B Global Operator
Laci Carvey, UST Class B Global Operator
Lisa Millspaugh, UST Class B Operator
Patrick Bakken, UST Class B Global Operator

Willy Baker, UST Class A Operator

Tank Code	01	Tank Age	42	Tank Installed Date	01/01/1980	Tank Material	Bare Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1348	Spill Test Date	05/04/2022	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	05/04/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	05/04/2022	Line Tightness Test Date	06/14/2010	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/04/2022			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	42	Tank Installed Date	01/01/1980	Tank Material	Bare Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1349	Spill Test Date	05/04/2022	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current

Report Created: 11/1/2022 Page [91] of [147]

Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	05/04/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	05/04/2022	Line Tightness Test Date	06/14/2010	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/04/2022			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	03	Tank Age	42	Tank Installed Date	01/01/1980	Tank Material	Bare Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1350	Spill Test Date	05/04/2022	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	05/04/2022	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date	05/04/2022	Line Tightness Test Date	06/14/2010	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/04/2022			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				

Location: NOONS 457

540 E Broadway St

Missoula, MT 59802-4614 Missoula

System Facility ID:32-03614

Facility Code: 25304 Last Inspected On: 05/18/2021 Operating Permit Renewal Date: 08/26/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Hi Noon Petroleum Missoula

Operator Contact: Andrew Young; Earl Allen; Erin Keffeler; John Monahan

4063967578

Owner/Operator: Hi Noon Petroleum Missoula

Allisa Gilstrap, UST Class B Global Operator Allisa Gilstrap, UST Class B Operator Andrew Young, UST Class A Operator Andrew Young, UST Class B Global Operator Cameron Fulmer, UST Class B Global Operator

Earl Allen, UST Class A Operator

Report Created: 11/1/2022 Page [92] of [147]

Earl Allen, UST Class B Operator
Erin Keffeler, UST Class A Operator
Erin Keffeler, UST Class B Global Operator
Holly Dale, UST Class B Global Operator
John Monahan, UST Class B Global Operator
John Monahan, UST Class B Global Operator
Laci Carvey, UST Class B Global Operator
Lisa Millspaugh, UST Class B Operator
Patrick Bakken, UST Class B Global Operator
Timothy Kamerman, UST Class B Operator
Willy Baker, UST Class B Global Operator

Tank Code	05	Tank Age	7	Tank Installed Date	04/28/2015	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5573	Spill Test Date	05/18/2021	Piping Installed Date	04/28/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/18/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	18000	ATG Test Date	05/18/2021	Line Tightness Test Date	02/13/2021	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	05/18/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	06	Tank Age	7	Tank Installed Date	04/28/2015	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5574	Spill Test Date	05/18/2021	Piping Installed Date	04/28/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/18/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date	05/18/2021	Line Tightness Test Date	02/13/2021	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes

Report Created: 11/1/2022 Page [93] of [147]

		Overfill Test Date	05/18/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				
Tank Code	07	Tank Age	7	Tank Installed Date	04/28/2015	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5575	Spill Test Date	05/18/2021	Piping Installed Date	04/28/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/18/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date	05/18/2021	Line Tightness Test Date	02/13/2021	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	05/18/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/8484 Series PLLD				

Location: NOONS 470

1605 S Russell St

Missoula, MT 59801-5636 Missoula

Facility Code: 25478

Last Inspected On: 09/30/2021
Operating Permit Renewal Date: 02/09/2025 System Facility ID:32-08863

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Hi Noon Petroleum Missoula

Operator Contact: Andrew Young; Earl Allen; Erin Keffeler; John Monahan

4063967578

Owner/Operator: Hi Noon Petroleum Missoula

Andrew Young, UST Class A Operator Andrew Young, UST Class B Global Operator Cameron Fulmer, UST Class B Global Operator Deven Cornell, UST Class B Global Operator

Earl Allen, UST Class A Operator Earl Allen, UST Class B Operator

Page [94] of [147] Report Created: 11/1/2022

Erin Keffeler, UST Class A Operator
Erin Keffeler, UST Class B Operator
Holly Dale, UST Class B Global Operator
John Monahan, UST Class A Operator
John Monahan, UST Class B Global Operator
Laci Carvey, UST Class B Global Operator
Lisa Millspaugh, UST Class B Operator
Patrick Bakken, UST Class B Global Operator
Willy Baker, UST Class B Global Operator

Tank Code	01	Tank Age	37	Tank Installed Date	06/23/1985	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1357	Spill Test Date	05/18/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	05/18/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/18/2021			ATG Type	Franklin Fueling Systems/TS- LLD;Veeder Root/TLS-300				
Tank Code	02	Tank Age	37	Tank Installed Date	06/23/1985	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1358	Spill Test Date	05/18/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	05/18/2021	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/18/2021			ATG Type	Franklin Fueling Systems/TS- LLD;Veeder Root/TLS-300				
Tank Code	03	Tank Age	37	Tank Installed Date	06/23/1985	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1359	Spill Test Date	05/18/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Report Created: 11/1/2022 Page [95] of [147]

Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	05/18/2021	Line Tightness Test Date	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	05/18/2021		ATG Type	Franklin Fueling Systems/TS- LLD;Veeder Root/TLS-300				

System Facility ID:32-04620

Location: OLES COUNTRY STORE 11

1600 S Russell St

Missoula, MT 59801-5637 Missoula

Facility Code: 25345
Last Inspected On: 10/29/2021
Operating Permit Renewal Date: 03/05/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: DDJ Investments LLC;Jennifer Louquet 4067287618

Operator Contact: Derek Louquet 4063695855

Owner/Operator: DDJ Investments LLC

Owner/Operator: Jennifer Louquet

Derek Louquet, UST Class A Operator Mary Fleming, UST Class B Operator

Tank Code	04	Tank Age	34	Tank Installed Date	10/30/1988	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1721	Spill Test Date	04/15/2022	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	02/16/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	10/27/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date	10/27/2021	Line Tightness Test Date	02/16/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/27/2021			ATG Type	Gilbarco/EMC Basic				
Tank Code	05	Tank Age	34	Tank Installed Date	10/30/1988	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1722	Spill Test Date	10/27/2021	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	02/16/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic

Page [96] of [147] Report Created: 11/1/2022

Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	10/27/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	10/27/2021	Line Tightness Test Date	02/16/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/27/2021			ATG Type	Gilbarco/EMC Basic				
Tank Code	06	Tank Age	34	Tank Installed Date	10/30/1988	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1723	Spill Test Date	10/27/2021	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	02/16/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	10/27/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date	10/27/2021	Line Tightness Test Date	02/16/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	10/27/2021			ATG Type	Gilbarco/EMC Basic				

Location: OLES COUNTRY STORE 12 and DIXIES DINER

3705 MT Hwy 200 E Missoula, MT 59802 Missoula

System Facility ID:32-03190

Facility Code: 25284 Last Inspected On: 09/23/2019 Operating Permit Renewal Date: 02/09/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: J Louquet;JGL Distributing Inc 4067287736

Operator Contact: Peggy Wolfe

Owner/Operator: J Gary Louquet

Owner/Operator: JGL Distributing Inc

LeeAnn Dean, UST Class B Global Operator

Peggy Wolfe, UST Class A Operator Peggy Wolfe, UST Class B Operator

Tank Code	01	Tank Age	58	Tank Installed Date	05/01/1964	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1427	Spill Test Date		Piping Installed Date	01/11/2018	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current

Page [97] of [147] Report Created: 11/1/2022

Product	Gasoline	PLLD Test Date	07/29/2019	Tank/Piping CP Test Date	09/23/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/21/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Veeder Root/8484 Series PLLD				
Tank Code	02	Tank Age	58	Tank Installed Date	05/01/1964	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1428	Spill Test Date		Piping Installed Date	01/11/2018	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	07/29/2019	Tank/Piping CP Test Date	09/23/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/21/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Veeder Root/8484 Series PLLD				
Tank Code	03	Tank Age	58	Tank Installed Date	05/01/1964	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1429	Spill Test Date		Piping Installed Date	01/11/2018	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	07/29/2019	Tank/Piping CP Test Date	09/23/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/21/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Veeder Root/8484 Series PLLD				
Tank Code	04	Tank Age	58	Tank Installed Date	05/01/1964	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1430	Spill Test Date		Piping Installed Date	01/11/2018	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current

Report Created: 11/1/2022 Page [98] of [147]

Product	Gasoline	PLLD Test Date	07/29/2019	Tank/Piping CP Test Date	09/23/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/21/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Veeder Root/8484 Series PLLD				
Tank Code	05	Tank Age	43	Tank Installed Date	05/02/1979	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1431	Spill Test Date		Piping Installed Date	01/11/2018	Tank Construction	Lined Interior/Impressed Current	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date	07/29/2019	Tank/Piping CP Test Date	09/23/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	04/21/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;Veeder Root/8484 Series PLLD				

Location: OLES COUNTRY STORE INC 2

923 N Orange St

Missoula, MT 59802-2927 Missoula

System Facility ID:32-05216

Facility Code: 25359 Last Inspected On: 11/05/2019 Operating Permit Renewal Date: 03/14/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Oles Country Stores Inc Missoula

Operator Contact: Casie Schwindt

Owner/Operator: Oles Country Stores Inc Missoula

Casie Schwindt, UST Class A Operator Casie Schwindt, UST Class B Operator Erika Nicklay, UST Class B Operator

Tank Code	04	Tank Age	32	Tank Installed Date	09/25/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
-----------	----	----------	----	------------------------	------------	---------------	---------------------------------	-----------------	------------------	----------------	------------------

Report Created: 11/1/2022 Page [99] of [147]

Tag Number	2357	Spill Test Date	11/05/2019	Piping Installed Date		Tank Construction		Piping Construction	Secondary Containment Chase	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	11/05/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	15000	ATG Test Date		Line Tightness Test Date	08/22/2007	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic;OPW Fuel Management/TS- LLD				
Tank Code	05	Tank Age	32	Tank Installed Date	09/25/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2358	Spill Test Date	11/05/2019	Piping Installed Date		Tank Construction		Piping Construction	Secondary Containment Chase	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	11/05/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	08/22/2007	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				
Tank Code	06	Tank Age	32	Tank Installed Date	09/25/1990	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	2359	Spill Test Date	11/05/2019	Piping Installed Date		Tank Construction		Piping Construction	Secondary Containment Chase	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	11/05/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	08/22/2007	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				

Location: PHILLIPS 66 EXXON MOBIL JOINTLY OWNED MISSOULA TERMINAL 3330 Raser Dr

Missoula, MT 59808-1534 Missoula

System Facility ID:32-08732

Facility Code: 25472 Last Inspected On: 02/24/2022 Operating Permit Renewal Date: 06/09/2025

Owner Operator Contact: Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal

4062555714

Operator Contact: Mark Shellabarger

Owner/Operator: Phillips 66/Exxon Mobil Jointly Owned Missoula

Terminal

Andrew Snyder, UST Class B Operator
Chris Binder, UST Class B Operator
Dusty Nagel, UST Class B Operator
Kyle Jackson, UST Class B Operator
Mark Shellabarger, UST Class A Operator
Mark Shellabarger, UST Class B Global Operator
Mark Shellabarger, UST Class B Operator
Orlando Rodriguez, UST Class B Operator

Tank Code	S15	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	2793	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	630000	ATG Test Date		Line Tightness Test Date	09/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	S18	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	2796	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	1260000	ATG Test Date		Line Tightness Test Date	09/07/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S19	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	

Report Created: 11/1/2022 Page [101] of [147]

			r	Piping Installed		Tank	r	Piping			<b></b>
Tag Number	2797	Spill Test Date		Date		Construction		Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	647892	ATG Test Date		Line Tightness Test Date	09/09/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S23	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	2800	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	847000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S24	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	2801	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	847000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S25	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	<u> </u>
Tag Number	2802	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	<u> </u>
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	648000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S26	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	

Report Created: 11/1/2022 Page [102] of [147]

Tag Number	2803	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	648000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S13	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	4581	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	630000	ATG Test Date		Line Tightness Test Date	09/07/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	S17	Tank Age	68	Tank Installed Date	06/01/1954	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	4909	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	840000	ATG Test Date		Line Tightness Test Date	09/08/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					

**Location:** PHILLIPS 66 EXXON MOBIL JOINTLY OWNED MISSOULA TERMINAL

3330 Raser Dr

Missoula, MT 59808-1534 Missoula

Facility Code: 25289 Last Inspected On: 02/24/2022 Operating Permit Renewal Date: 06/09/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal 4062555714

System Facility ID:32-03320

Operator Contact: Adam Pfeifer; Dusty Nagel; Mark Shellabarger

Page [103] of [147] Report Created: 11/1/2022

Owner/Operator: Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal

Adam Pfeifer, UST Class A Operator

Adam Pfeifer, UST Class B Global Operator

Andrew Snyder, UST Class B Operator

Brent Schreckendgust, UST Class B Operator

Chris Binder, UST Class B Operator

Dustin Rogers, UST Class B Operator

Dusty Nagel, UST Class A Operator

Dusty Nagel, UST Class B Operator

Kerry Sweten, UST Class B Operator

Kyle Jackson, UST Class B Operator

Marcus Eppard, UST Class B Operator

Mark Shellabarger, UST Class A Operator

Mark Shellabarger, UST Class B Global Operator

Mark Shellabarger, UST Class B Operator

Michael McArthur, UST Class B Operator

Orlando Rodriguez, UST Class B Operator

Randy Dayley, UST Class B Operator

Tank Code	22	Tank Age	25	Tank Installed Date	11/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Steel - Terminal Piping	Overfill Types	High Level Alarm
Tag Number	738	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Gravity Feed	CP Met Types	
Product	Mixture	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	09/28/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	S09	Tank Age	69	Tank Installed Date	01/01/1953	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	739	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	1260000	ATG Test Date		Line Tightness Test Date	09/14/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

Report Created: 11/1/2022 Page [104] of [147]

Tank Code	S11	Tank Age	69	Tank Installed Date	01/01/1953	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	741	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	840000	ATG Test Date		Line Tightness Test Date	09/22/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S13	Tank Age	69	Tank Installed Date	01/01/1953	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	743	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Mixture	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	840000	ATG Test Date		Line Tightness Test Date	09/16/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S15	Tank Age	69	Tank Installed Date	01/01/1953	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	745	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasohol/Etha nol	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	840000	ATG Test Date		Line Tightness Test Date	09/10/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S17	Tank Age	50	Tank Installed Date	01/01/1972	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	747	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	840000	ATG Test Date		Line Tightness Test Date	09/22/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					T

Report Created: 11/1/2022 Page [105] of [147]

Tank Code	S19	Tank Age	48	Tank Installed Date	01/01/1974	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	749	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	4200000	ATG Test Date		Line Tightness Test Date	09/22/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	S20	Tank Age	48	Tank Installed Date	01/01/1974	Tank Material	Cathodically Protected Steel	Piping Material	Steel - Terminal Piping	Overfill Types	
Tag Number	750	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/10/2019	Primary Tank Leak Detection		Primary Pipe Detection	Terminal Piping Annual Line Test	Vapor Recovery	No
Capacity	2646000	ATG Test Date		Line Tightness Test Date	09/15/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					

Location: PROVIDENCE CENTER

900 N Orange St

Missoula, MT 59802-2998 Missoula

System Facility ID:32-13405

Facility Code: 25746
Last Inspected On: 02/15/2021
Operating Permit Renewal Date: 04/03/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Saint Patricks Hospital 4065437271

Operator Contact: Timothy Chopp

Owner/Operator: Saint Patricks Hospital

Harry McGuire, UST Class B Operator Timothy Chopp, UST Class A Operator Timothy Chopp, UST Class B Operator

Tank Code	02	Tank Age	27	Tank Installed Date	08/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm
-----------	----	----------	----	------------------------	------------	---------------	----------------------------------	-----------------	------------------	----------------	--------------------------------------

Report Created: 11/1/2022 Page [106] of [147]

Tag Number	1960	Spill Test Date	 Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	 Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	2500	ATG Test Date	 Line Tightness Test Date	02/12/2021	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date			ATG Type	Gilbarco-Veeder Root/TLS- 300;Veeder Root/TLS-300				

Location: PS MINI MART 930 N Russell St

Missoula, MT 59808 Missoula

Facility Code: 25751 Last Inspected On: 12/21/2020 Operating Permit Renewal Date: 01/06/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Christine Denning 4068807272

Operator Contact: Scott Denning 4068807272

Owner/Operator: Christine Denning

Scott Denning, UST Class A Operator Scott Denning, UST Class B Operator

Tank Code	01		r	Tank Installed			Fiberglass		Fiborglass		r
Talik Code	O1	Tank Age	28	Date	06/01/1994	Tank Material	Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1450	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	12/17/2020	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	08/04/2011	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	12/17/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	28	Tank Installed Date	06/01/1994	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Report Created: 11/1/2022 Page [107] of [147]

Tag Number	1451	Spill Test Date	[	Piping Installed Date	[	Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	12/17/2020	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	08/04/2011	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	12/17/2020	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	03	Tank Age	28	Tank Installed Date	06/01/1994	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1452	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	12/17/2020	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	08/04/2011	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	01/12/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Report Created: 11/1/2022 Page [108] of [147]

Location: RANGITSCH BROTHERS 2001 WEST BROADWAY

2001 W Broadway St

Missoula, MT 59808-1817 Missoula

System Facility ID:32-09919

Facility Code: 25529
Last Inspected On: 07/22/2020
Operating Permit Renewal Date: 10/29/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Rangitsch Brothers 4067284040

Operator Contact: Gerry Wolner; Joel Jasperson 4067217561

Owner/Operator: Rangitsch Brothers

David Crowder, UST Class B Operator Gerry Wolner, UST Class A Operator Joel Jasperson, UST Class A Operator Joel Jasperson, UST Class B Operator Russ Dickey, UST Class B Operator

Tank Code	03	Tank Age	23	Tank Installed Date	01/01/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	3917	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	EMCO Electronics/EECO 1500				

#### Facility Summary in Missoula County in the City of Missoula

System Facility ID:60-15318

Location: ROSAUERS 127 FUEL STATION

2350 S Reserve St

Missoula, MT 59801 Missoula

Facility Code: 31015 Last Inspected On: 11/08/2021

Operating Permit Renewal Date: 12/23/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Rosauers Supermarkets Inc Marshall 5093268900

Report Created: 11/1/2022 Page [109] of [147]

## Owner/Operator: Rosauers Supermarkets Inc Marshall

Jerry Kuykendall, UST Class B Global Operator

Keith Wolf, UST Class A Operator

Keith Wolf, UST Class B Global Operator Paco Sutton, UST Class A Operator

Paco Sutton, UST Class B Operator

Tank Code	01	Tank Age	4	Tank Installed Date	06/21/2018	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm
Tag Number	5814	Spill Test Date	08/31/2021	Piping Installed Date	06/24/2018	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/24/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	20000	ATG Test Date	09/01/2021	Line Tightness Test Date		Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	12/01/2021			ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	02	Tank Age	4	Tank Installed Date	06/21/2018	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm
Tag Number	5815	Spill Test Date	08/31/2021	Piping Installed Date	06/24/2018	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/24/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	9000	ATG Test Date	09/01/2021	Line Tightness Test Date		Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	12/01/2021			ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				
Tank Code	03	Tank Age	4	Tank Installed Date	06/21/2018	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm

Report Created: 11/1/2022 Page [110] of [147]

Tag Number	5816	Spill Test Date	08/31/2021	Piping Installed Date	06/24/2018	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	06/24/2018	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	6000	ATG Test Date	09/01/2021	Line Tightness Test Date		•	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	12/01/2021			ATG Type	Franklin Fueling Systems/TS- LS500 Series;Incon/TS- 550 EVO				

Location: SILVER SLIPPER

4055 Hwy 93 S

Missoula, MT 59804-7300 Missoula

Facility Code: 25780 Last Inspected On: 11/25/2020 Operating Permit Renewal Date: 11/25/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact:Kathy Ogren; Preslyn LLC4062512525; 4062515402

Operator Contact: Melissa Rausch 4062534921

Owner/Operator: Kathy Ogren

Owner/Operator: Preslyn LLC

Melissa Rausch, UST Class A Operator Melissa Rausch, UST Class B Operator

Tank Code	01	Tank Age	26	Tank Installed Date	03/01/1996	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3251	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	15000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

Report Created: 11/1/2022 Page [111] of [147]

Tank Code	02	Tank Age	26	Tank Installed Date	03/01/1996	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3252	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	15000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	03	Tank Age	26	Tank Installed Date	03/01/1996	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3253	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					

Report Created: 11/1/2022 Page [112] of [147]

Location: SORENSEN TRANSPORT

6575 US Hwy 10 W

Missoula, MT 59808-9086 Missoula

Facility Code: 25748
Last Inspected On: 05/12/2021
System Facility ID:32-13428 Operating Permit Renewal Date: 10/15/2024

. .

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Sorensen Transport 4067215404

Operator Contact: Lane Sorensen 4067215404

Owner/Operator: Sorensen Transport

Lane Sorensen, UST Class A Operator Lane Sorensen, UST Class B Operator

Tank Code	02	Tank Age	7	Tank Installed Date	06/04/2015	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	5576	Spill Test Date		Piping Installed Date	06/04/2015	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/19/2015	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/09/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	20000	ATG Test Date	05/09/2022	Line Tightness Test Date	06/03/2015	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	ELLD 0.2	Energy Act	Yes
		Overfill Test Date	05/09/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				

#### Facility Summary in Missoula County in the City of Missoula

Location: SOUTH AVENUE MARKET #11

2401 S Higgins Ave

Missoula, MT 59801 Missoula

Facility Code: 25381 Last Inspected On: 09/24/2019

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Hi-Star Properties LLC

Report Created: 11/1/2022 Page [113] of [147]

Owner/Operator: Hi-Star Properties LLC

Steven Schmidt, UST Class A Operator

Tank Code	02	Tank Age	41	Tank Installed Date	04/26/1981	Tank Material	Bare Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3849	Spill Test Date	08/18/2020	Piping Installed Date	07/21/2000	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	07/15/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	08/18/2020			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				
Tank Code	03	Tank Age	41	Tank Installed Date	04/26/1981	Tank Material	Bare Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3850	Spill Test Date	08/18/2020	Piping Installed Date	07/21/2000	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	07/15/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	08/18/2020			ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco/EM C Basic				
Tank Code	01	Tank Age	41	Tank Installed Date	04/26/1981	Tank Material	Bare Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	4668	Spill Test Date	08/18/2020	Piping Installed Date	07/21/2000	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	08/18/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [114] of [147]

Overfill Test Date

08/18/2020

ATG Type

Franklin Fueling Systems/TS-LLD;Gilbarco/EM C Basic

#### Facility Summary in Missoula County in the City of Missoula

Location: SOUTHGATE MARKET

1900 South Ave W

Missoula, MT 59801-6508 Missoula

Facility Code: 25477 Last Inspected On: 02/02/2021

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Fugli LLC;Steve Hintz 4063701314;4065422685

Operator Contact: Diana Hintz;Steve Hintz 4063701314;4065422685

Owner/Operator: Fugli LLC

Owner/Operator: Steve Hintz

Diana Hintz, UST Class A Operator Gary Keith, UST Class B Operator Steve Hintz, UST Class A Operator

Tank Code	01	Tank Age	37	Tank Installed Date	12/23/1985	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1354	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	02/02/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	10/12/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				
Tank Code	02	Tank Age	37	Tank Installed Date	12/23/1985	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1355	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Report Created: 11/1/2022 Page [115] of [147]

Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	02/02/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	10/20/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				
Tank Code	03	Tank Age	37	Tank Installed Date	12/23/1985	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	1356	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	02/02/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	10/20/2017	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/				

Report Created: 11/1/2022 Page [116] of [147]

Location: SPRINT MISSOULA POP

2515 Railroad St W

Missoula, MT 59808-1680 Missoula

System Facility ID:56-14010

Facility Code: 30670
Last Inspected On: 06/08/2020
Operating Permit Renewal Date: 08/12/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Sprint Communications Co LLP 9137625957

Operator Contact: Brian Wiedower 9133158631

Owner/Operator: Sprint Communications Co LLP

Brian Wiedower, UST Class A Operator Matt Santee, UST Class B Global Operator Nikki Lattin, UST Class B Global Operator Scott Hallesy, UST Class B Operator

Tank Code	01	Tank Age	21	Tank Installed Date	06/01/2001		Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm
Tag Number	4321	Spill Test Date	05/12/2020	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test;Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	2500	ATG Test Date	05/09/2022	Line Tightness Test Date	05/09/2022	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	05/09/2022			ATG Type	Gilbarco-Veeder Root/TLS-300				

## Facility Summary in Missoula County in the City of Missoula

Location: ST PATRICKS HOSPITAL

500 W Broadway St

Missoula, MT 59802-4008 Missoula

Facility Code: 25338 Last Inspected On: 02/15/2021

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Report Created: 11/1/2022 Page [117] of [147]

Operator Contact: Timothy Chopp

Owner/Operator: Saint Patricks Hospital

Timothy Chopp, UST Class A Operator Timothy Chopp, UST Class B Operator

Tank Code	03	Tank Age	21	Tank Installed Date	10/01/2001	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve;High Level Alarm
Tag Number	4497	Spill Test Date		Piping Installed Date	02/29/2008	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	02/12/2021	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 300;Veeder Root/TLS-300				
Tank Code	04	Tank Age	14	Tank Installed Date	07/18/2008	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm;Positive Shutoff
Tag Number	5175	Spill Test Date		Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Auto Dialer	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	3-Year Line Tightness Test	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	02/12/2021	Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 300;Veeder Root/TLS-300				

4065437271

Facility Summary in Missoula County in the City of Missoula

Report Created: 11/1/2022 Page [118] of [147]

Location: TABISH BROTHERS DISTRIBUTORS INC

501 Taylor St Missoula, MT 59802-4920 Missoula

System Facility ID:32-06523

Facility Code: 25407 Last Inspected On: 04/25/2020 Operating Permit Renewal Date: 06/22/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Tabish Brothers Distributors Inc 4065437621

Operator Contact: Heather Stiles

Owner/Operator: Tabish Brothers Distributors Inc

Heather Stiles, UST Class A Operator Heather Stiles, UST Class B Global Operator

Tank Code	01	Tank Age	41	Tank Installed Date	04/16/1981	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	2080	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	U.S. Suction	CP Met Types	Non-corrodible
Product	Heating Oil	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.1;Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	7600	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	41	Tank Installed Date	04/16/1981	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	2081	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/23/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring	Piping Type	Gravity Feed	CP Met Types	Non-corrodible
Product	Oil, Waste	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	7600	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Page [119] of [147] Report Created: 11/1/2022

Location: THE OLDE DAIRY 2106 Clements Rd

Missoula, MT 59804-6212 Missoula

System Facility ID:32-08475

Facility Code: 25464
Last Inspected On: 08/25/2020
Operating Permit Renewal Date: 09/03/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

 Owner Operator Contact:
 Dale Johnson; Target Range Development LLC
 4067213322

Operator Contact: Madison Jones;Mark Jones 4062397387;4067213322

Owner/Operator: Dale L Johnson

Owner/Operator: Target Range Development LLC

Madison Jones, UST Class A Operator Madison Jones, UST Class B Operator Mark Jones, UST Class A Operator Mark Jones, UST Class B Operator

Tank Code	05	Tank Age	23	Tank Installed Date	03/23/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4086	Spill Test Date	04/19/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	06	Tank Age	23	Tank Installed Date	03/23/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4087	Spill Test Date	04/19/2022	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/30/2020	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No

Report Created: 11/1/2022 Page [120] of [147]

Capacity	8000	ATG Test Date		Line Tightness Test Date	02/01/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	07	Tank Age	23	Tank Installed Date	03/23/1999	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	4088	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 350/Gilbarco EMC				

Location: TOWN PUMP INC MISSOULA 1

5310 Grant Creek Rd

Missoula, MT 59808-1483 Missoula

Facility Code: 25739

Last Inspected On: 05/08/2021 System Facility ID:32-13336 Operating Permit Renewal Date: 05/08/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Missoula 1 Town Pump LLC 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Missoula 1 Town Pump LLC

Owner/Operator: Town Pump Inc

Charles Armstrong, UST Class A Operator Charles Armstrong, UST Class B Global Operator

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code 01 Tank Age 29 Tank Installed Date 12/01/1993 Tank Material Fiberglass Reinforced Plastic Piping Material Fiberglass Reinforced Plastic Overfill Types Flapper Valve

Report Created: 11/1/2022 Page [121] of [147]

Tag Number	2342	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	03/19/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	Yes
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	02	Tank Age	29	Tank Installed Date	12/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2343	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	03/19/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	Yes
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	03	Tank Age	29	Tank Installed Date	12/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2344	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Single Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	03/19/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	Yes
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	04	Tank Age	29	Tank Installed Date	12/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2345	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	

Report Created: 11/1/2022 Page [122] of [147]

			[				Statistical		Statistical		T
Product	Diesel	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	03/19/2019	Primary Tank Leak Detection	Inventory Reconciliation	Primary Pipe Detection	Inventory Reconciliation	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350;Veeder Root/8484 Series PLLD				
Tank Code	05	Tank Age	13	Tank Installed Date	01/25/2009	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5196	Spill Test Date		Piping Installed Date	01/25/2009	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/04/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	01/11/2010	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	Yes
Capacity	20000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	06	Tank Age	13	Tank Installed Date	01/25/2009	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	5197	Spill Test Date		Piping Installed Date	01/25/2009	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/04/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	01/11/2010	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Location: TOWN PUMP INC MISSOULA 2

318 S Orange St

Missoula, MT 59801-1811 Missoula

Facility Code: 25471 Last Inspected On: 05/04/2021 Operating Permit Renewal Date: 05/07/2024

System Facility ID:32-08715

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Page [123] of [147] Report Created: 11/1/2022

4064976700

Operator Contact: Trent Biggers

Owner/Operator: Missoula 2 Town Pump LLC

Trent Biggers, UST Class A Operator Trent Biggers, UST Class B Global Operator

Tank Code	04	Tank Age	32	Tank Installed Date	05/24/1990	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2552	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	05/04/2021	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	05	Tank Age	32	Tank Installed Date	05/29/1990	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2553	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	05/04/2021	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	06	Tank Age	32	Tank Installed Date	05/29/1990	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2554	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date	05/04/2021	Tank/Piping CP Test Date	05/04/2021	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No

Report Created: 11/1/2022 Page [124] of [147]

Capacity	10000	ATG Test Date	Line Tightness Test Date	Secondary Tank Leak Detection		Secondary Pipe Detection	 Energy Act	No
		Overfill Test Date		ATG Type	Gilbarco-Veeder Root/TLS-350			

Location: TOWN PUMP INC MISSOULA 3

2210 N Reserve St

Missoula, MT 59808-1323 Missoula

Facility Code: 25725
Last Inspected On: 05/08/2021
Operating Permit Renewal Date: 05/08/2024 System Facility ID:32-13172

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Missoula 3 Town Pump LLC 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Missoula 3 Town Pump LLC

Trent Biggers, UST Class A Operator Trent Biggers, UST Class B Global Operator

Tank Code	01	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2559	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/05/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	09/22/2006	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	02	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2560	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/05/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No

Page [125] of [147] Report Created: 11/1/2022

Capacity	12000	ATG Test Date		Line Tightness Test Date	09/22/2006	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	03	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2561	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/05/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	09/30/2006	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	04	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2562	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/05/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	09/30/2006	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	05	Tank Age	29	Tank Installed Date	06/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	2563	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/05/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Statistical Inventory Reconciliation	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	09/30/2006	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Report Created: 11/1/2022 Page [126] of [147]

Location: TOWN PUMP INC MISSOULA 8

3420 Mullan Rd Ste A

Missoula, MT 59808-5126 Missoula

System Facility ID:56-13823

Facility Code: 30509
Last Inspected On: 04/27/2021
Operating Permit Renewal Date: 10/01/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Missoula 8 Town Pump LLC 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Missoula 8 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	01	Tank Age	25	Tank Installed Date	08/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	1444	Spill Test Date	06/14/2019	Piping Installed Date	05/24/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	04/27/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	05/05/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	02	Tank Age	25	Tank Installed Date	08/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	1445	Spill Test Date		Piping Installed Date	05/24/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	04/27/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date	05/18/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Report Created: 11/1/2022 Page [127] of [147]

Tank Code	03	Tank Age	25	Tank Installed Date	08/01/1997	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	1446	Spill Test Date		Piping Installed Date	05/24/2016	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	04/27/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date	05/17/2016	Secondary Tank Leak Detection		Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	04	Tank Age	6	Tank Installed Date	05/24/2016	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	5629	Spill Test Date		Piping Installed Date	05/24/2016	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	04/27/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	04/27/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	05/18/2016	Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-350				

Location: TOWN PUMP MISSOULA 9

2001 Brooks St

Missoula, MT 59808 Missoula

Facility Code: 30995 Last Inspected On: 05/10/2021

System Facility ID:60-15288 Operating Permit Renewal Date: 05/14/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

 Owner Operator Contact:
 Missoula 9 Town Pump LLC
 4064976700

Operator Contact: Trent Biggers

Owner/Operator: Missoula 9 Town Pump LLC

Trent Biggers, UST Class A Operator Trent Biggers, UST Class B Operator

Report Created: 11/1/2022 Page [128] of [147]

Tank Code	01	Tank Age	5	Tank Installed Date	03/28/2017	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	5683	Spill Test Date	04/14/2020	Piping Installed Date	03/28/2017	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/10/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	25000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	02	Tank Age	5	Tank Installed Date	03/28/2017	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	5684	Spill Test Date	04/14/2020	Piping Installed Date	03/28/2017	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	05/10/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	Yes
Capacity	15000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-450				
Tank Code	03	Tank Age	5	Tank Installed Date	03/28/2017	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	5685	Spill Test Date	04/14/2020	Piping Installed Date	03/28/2017	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date	05/10/2021	Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	05/10/2021	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	15000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Statistical Inventory Reconciliation	Secondary Pipe Detection	Statistical Inventory Reconciliation	Energy Act	Yes
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS-450				

Report Created: 11/1/2022 Page [129] of [147]

Location: UNITED PARCEL SERVICES MISSOULA

221 Expressway Ln

Missoula, MT 59808-1553 Missoula

Facility Code: 25343 Last Inspected On: 04/18/2022

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

 Owner Operator Contact:
 United Parcel Service Inc Seattle
 2066216380

Operator Contact: Dino Ostrow; Kaytee Villafrancaa; Treair Smith 2066216286; 2066216380; 5033297154

## Owner/Operator: United Parcel Service Inc Seattle

Dino Ostrow, UST Class A Operator
Dino Ostrow, UST Class B Operator
Kaytee Villafrancaa, UST Class A Operator
Kaytee Villafrancaa, UST Class B Global Operator

Treair Smith, UST Class A Operator Treair Smith, UST Class B Global Operator

Tank Code	04	Tank Age	29	Tank Installed Date	07/01/1993	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2182	Spill Test Date	04/18/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	04/18/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	12000	ATG Test Date	04/18/2022	Line Tightness Test Date	04/18/2022	Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	04/26/2022			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/Red Jacket FXIV				

#### Facility Summary in Missoula County in the City of Missoula

Location: WESTERN TRANSPORT

9310 Cartage Rd

Missoula, MT 59808-9758 Missoula

Facility Code: 25211 Last Inspected On: 05/11/2022

System Facility ID:32-01348 Operating Permit Renewal Date: 06/09/2025

Report Created: 11/1/2022 Page [130] of [147]

Owner Operator Contact: Western Land Investments LLC

Operator Contact: Cari Goss;Neil Hanson;Scott Allen

3076746305;4064937876

# Owner/Operator: Western Land Investments LLC

Cari Goss, UST Class A Operator
Neil Hanson, UST Class A Operator
Neil Hanson, UST Class B Global Operator
Robin Titus, UST Class B Global Operator
Scott Allen, UST Class A Operator
Scott Allen, UST Class B Operator

Tank Code	01	Tank Age	54	Tank Installed Date	01/17/1968	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	High Level Alarm
Tag Number	1654	Spill Test Date	09/29/2021	Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	09/29/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	10000	ATG Test Date	09/30/2021	Line Tightness Test Date	09/12/2012	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS- 250				
Tank Code	02	Tank Age	54	Tank Installed Date	01/17/1968	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm
Tag Number	1655	Spill Test Date	09/29/2021	Piping Installed Date	12/11/2006	Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date	03/22/2022	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	09/29/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	09/30/2021	Line Tightness Test Date	03/22/2022	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Veeder Root/TLS- 250				
Tank Code	03	Tank Age	41	Tank Installed Date	01/16/1981	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	High Level Alarm

Report Created: 11/1/2022 Page [131] of [147]

Tag Number	1656	Spill Test Date	Piping Installed Date	12/11/2006	Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Temporarily Out of Use	MLLD Test Date	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Impressed Current
Product	Diesel	PLLD Test Date	Tank/Piping CP Test Date	09/29/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	Line Tightness Test Date	05/27/2010	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date			ATG Type	Veeder Root/TLS- 250				

System Facility ID:32-13674

Location: WESTFIELD MISSOULA

8448 US Hwy 10 W

Missoula, MT 59808-9319 Missoula

Facility Code: 25776

Last Inspected On: 04/20/2020 Operating Permit Renewal Date: 07/22/2023

oporating roman roman batter office con

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Finest Oil Co 4065436969

Operator Contact: Christopher Glasser; David Peyton; James Brady; James

DeWaters; Justin Gaudot; Stephen Hanson

4062181563;4063606327;4065436969;4065441005;7143338926

Owner/Operator: Finest Oil Co

Christopher Glasser, UST Class A Operator
David Peyton, UST Class A Operator
David Peyton, UST Class B Global Operator
James Brady, UST Class A Operator
James DeWaters, UST Class A Operator
Joseph McClain, UST Class B Operator
Justin Gaudot, UST Class A Operator
Justin Gaudot, UST Class B Global Operator
Stephen Hanson, UST Class A Operator

Stephen Hanson, UST Class B Operator

Tank Code	01	Tank Age	27	Tank Installed Date	12/01/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1077	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/14/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No

Report Created: 11/1/2022 Page [132] of [147]

Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	27	Tank Installed Date	12/01/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1078	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	04/14/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	03	Tank Age	27	Tank Installed Date	12/01/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1079	Spill Test Date		Piping Installed Date	09/19/2007	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/14/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	04	Tank Age	27	Tank Installed Date	12/01/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1080	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/14/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Report Created: 11/1/2022 Page [133] of [147]

Tank Code	05	Tank Age	27	Tank Installed Date	12/01/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1081	Spill Test Date		Piping Installed Date	05/17/2012	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/14/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	Continuous Interstitial Monitoring	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection	ELLD 0.2	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	06	Tank Age	27	Tank Installed Date	12/01/1995	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1082	Spill Test Date		Piping Installed Date	05/17/2012	Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	04/14/2020	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Location: YOKE'S FRESH MARKET 21

800 W Broadway St

Missoula, MT 59802-3944 Missoula

Facility Code: 30858 Last Inspected On: 05/13/2021

System Facility ID:60-15098 Operating Permit Renewal Date: 06/11/2024

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: YOKE'S FOOD INC 5099212292

Operator Contact: Aaron Nelson;Lynn Pehrson;Rebecca Spicer;Shari

Goodmanson

4062517170;4067212549;4252016301

Owner/Operator: YOKE'S FOOD INC

Aaron Nelson, UST Class A Operator Cathie Hinds, UST Class B Global Operator Lynn Pehrson, UST Class A Operator

Report Created: 11/1/2022 Page [134] of [147]

Rebecca Spicer, UST Class A Operator Rebecca Spicer, UST Class B Operator Shari Goodmanson, UST Class A Operator Shari Goodmanson, UST Class B Global Operator

Tank Code	01	Tank Age	14	Tank Installed Date	08/08/2008	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5167	Spill Test Date	05/13/2021	Piping Installed Date	07/01/2008	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	Yes
		Overfill Test Date	05/13/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	14	Tank Installed Date	08/01/2008	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5168	Spill Test Date	05/13/2021	Piping Installed Date	07/01/2008	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Continuous Interstitial Monitoring	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	Yes
		Overfill Test Date	05/13/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	03	Tank Age	14	Tank Installed Date	08/01/2008	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	5169	Spill Test Date	05/13/2021	Piping Installed Date	07/01/2008	Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection	Automatic Tank Gauging 0.2	Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	Yes

Report Created: 11/1/2022 Page [135] of [147]

#### 

### Facility Summary in Missoula County in the City of Missoula

Location: YOKES FRESH MARKET 22

3801 S Reserve St

Missoula, MT 59801-7322 Missoula

Facility Code: 30684 Last Inspected On: 07/12/2022

System Facility ID:56-14025 Operating Permit Renewal Date: 01/04/2026

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: YOKE'S FOOD INC 5099212292

Operator Contact: Aaron Nelson; Charles Franklin; Lynn Pehrson; Shari

Goodmanson

4062517170;4252016301

# Owner/Operator: YOKE'S FOOD INC

Aaron Nelson, UST Class A Operator
Allen Trimp, UST Class B Global Operator
Betty Heidrick, UST Class B Operator
Charles Franklin, UST Class A Operator
Charles Franklin, UST Class B Global Operator
Lynn Pehrson, UST Class A Operator

Shari Goodmanson, UST Class A Operator Shari Goodmanson, UST Class B Global Operator

Tank Code	01	Tank Age	21	Tank Installed Date	09/01/2001	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	4416	Spill Test Date	07/12/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	07/12/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	20000	ATG Test Date	07/12/2022	Line Tightness Test Date	01/16/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/12/2022			ATG Type	Gilbarco-Veeder Root/TLS-350				

Report Created: 11/1/2022 Page [136] of [147]

Tank Code	02	Tank Age	21	Tank Installed Date	09/01/2001	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	4417	Spill Test Date	07/12/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date	07/12/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	07/12/2022	Line Tightness Test Date	01/17/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/12/2022			ATG Type	Gilbarco-Veeder Root/TLS-350				
Tank Code	03	Tank Age	21	Tank Installed Date	09/01/2001	Tank Material	Steel Clad	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve;High Level Alarm
Tag Number	4418	Spill Test Date	07/12/2022	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date	07/12/2022	Tank/Piping CP Test Date		Primary Tank Leak Detection	Continuous Interstitial Monitoring	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date	07/12/2022	Line Tightness Test Date	07/09/2022	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date	07/12/2022			ATG Type	Gilbarco-Veeder Root/TLS-350				

Location: ZIP TRIP 31

3325 Brooks St

Missoula, MT 59801-8289 Missoula

Facility Code: 25516 Last Inspected On: 02/25/2022

System Facility ID:32-09730 Operating Permit Renewal Date: 05/20/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: CHS Inc Spokane Valley 5095357701

Operator Contact: Jason Cocke; Jim Alford; Sean Hurley 5095357701; 5095367418

Owner/Operator: CHS Inc Spokane Valley

Jason Cocke, UST Class A Operator

Report Created: 11/1/2022 Page [137] of [147]

Jason Cocke, UST Class B Global Operator
Jason Cocke, UST Class B Operator
Jim Alford, UST Class A Operator
Jim Alford, UST Class B Global Operator
Justin Mace, UST Class B Operator
Luci Tuttle, UST Class B Operator
Sean Hurley, UST Class A Operator

Tank Code	01	Tank Age	34	Tank Installed Date	03/18/1988	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1363	Spill Test Date	08/31/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/01/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	08/04/2010	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	07/01/2021	Line Tightness Test Date	07/01/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	08/31/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Vaporless Manufacturing/Va porless 99LD- 2000				
Tank Code	02	Tank Age	34	Tank Installed Date	03/18/1988	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1364	Spill Test Date	08/31/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/01/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	08/04/2010	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	07/01/2021	Line Tightness Test Date	07/01/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	08/31/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/Red Jacket FXIV				
Tank Code	03	Tank Age	34	Tank Installed Date	03/18/1988	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1365	Spill Test Date	08/31/2021	Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date	07/01/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible

Report Created: 11/1/2022 Page [138] of [147]

Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	08/04/2010	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	10000	ATG Test Date	07/01/2021	Line Tightness Test Date	07/01/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	08/31/2021			ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC;Veeder Root/Red Jacket FXIV				

System Facility ID:32-03912

Location: ZIP TRIP 32

1540 Toole Ave

Missoula, MT 59802-2241 Missoula

Facility Code: 25317

Last Inspected On: 10/27/2022 Operating Permit Renewal Date: 02/04/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: CHS Inc Spokane Valley 5095357701

Operator Contact: Jason Cocke; Jim Alford; Sean Hurley 5095357701; 5095367418

## Owner/Operator: CHS Inc Spokane Valley

Jason Cocke, UST Class A Operator
Jason Cocke, UST Class B Global Operator
Jason Cocke, UST Class B Operator
Jim Alford, UST Class A Operator
Jim Alford, UST Class B Global Operator
Justin Mace, UST Class B Operator
Luci Tuttle, UST Class B Operator
Sean Hurley, UST Class A Operator

Tank Code	01	Tank Age	38	Tank Installed Date	03/22/1984	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1342	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	07/11/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	04/13/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No

Report Created: 11/1/2022 Page [139] of [147]

		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	02	Tank Age	38	Tank Installed Date	03/22/1984	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1343	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	07/11/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	10000	ATG Test Date		Line Tightness Test Date	07/02/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
Tank Code	03	Tank Age	38	Tank Installed Date	03/22/1984	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	1344	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	07/11/2019	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity 1	10000	ATG Test Date		Line Tightness Test Date	06/25/2019	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

Location: ZOOTOWN SUPER STOP

2105 S Higgins Ave Missoula, MT 59801-6714 Missoula

Facility Code: 25429 Last Inspected On: 01/29/2021 Operating Permit Renewal Date: 03/13/2024

System Facility ID:32-07244

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Greg Tabish 4067282575

Operator Contact: Daniel Marx; Erin Keffeler; Karly Shafer; Yvonne Bunch 4062742435;4063962206;4068800056

Owner/Operator: Greg Tabish

Page [140] of [147] Report Created: 11/1/2022

Daniel Marx, UST Class A Operator
Daniel Marx, UST Class B Global Operator
Erin Keffeler, UST Class A Operator
Erin Keffeler, UST Class B Operator
Karly Shafer, UST Class A Operator
Karly Shafer, UST Class B Global Operator
Yvonne Bunch, UST Class A Operator
Yvonne Bunch, UST Class B Operator

Tank Code	03	Tank Age	32	Tank Installed Date	12/07/1990	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1799	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	01/26/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	07/13/2011	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic				
Tank Code	04	Tank Age	32	Tank Installed Date	12/07/1990	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1800	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	01/26/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	6000	ATG Test Date		Line Tightness Test Date	07/13/2011	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic				
Tank Code	05	Tank Age	32	Tank Installed Date	12/07/1990	Tank Material	Cathodically Protected Steel	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	1801	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	01/26/2021	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date	07/13/2011	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Gilbarco/EMC Basic				

Report Created: 11/1/2022 Page [141] of [147]

#### Facility Summary in Missoula County in the City of Seeley Lake

Location: LINDEYS LANDING WEST SPB

MT Hwy 83 Seeley Lake, MT 59868 Missoula

Facility Code: 25389 Last Inspected On: 09/09/2020 Operating Permit Renewal Date: 10/17/2023

System Facility ID:32-05837

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Lindeys Inc Saint Paul 4066779229

Operator Contact: Michael Lindemer 4066774101

Owner/Operator: Lindeys Inc Saint Paul

Michael Lindemer, UST Class A Operator Michael Lindemer, UST Class B Operator Tanner Stevenson, UST Class B Global Operator

Tank Code	S3	Tank Age	23	Tank Installed Date	05/01/1999	Tank Material	Concrete	Piping Material	Flexible Plastic	Overfill Types	High Level Alarm
Tag Number	4104	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	12/30/2021	Sump Tightness Test Date	09/08/2020	Catastrophic L.D Type 3.0	Continuous Interstitial Monitoring;Mecha nical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	1500	ATG Test Date		Line Tightness Test Date	10/25/2021	Secondary Tank Leak Detection		Secondary Pipe Detection	Continuous Interstitial Monitoring	Energy Act	No
		Overfill Test Date				ATG Type	Vaporless Manufacturing/Va porless 99LD- 2000				

#### Facility Summary in Missoula County in the City of Seeley Lake

Location: ROVEROS

3182 Hwy 83

Seeley Lake, MT 59868 Missoula

Facility Code: 30890 Last Inspected On: 12/13/2019

System Facility ID:60-15146 Operating Permit Renewal Date: 01/28/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Page [142] of [147] Report Created: 11/1/2022

Operator Contact: Karly Shafer;Kyle Marx

4063962206;4063962296

Owner/Operator: Addrien Marx

Owner/Operator: Greg Tabish

Owner/Operator: Roveros LLC

Owner/Operator: Tabish Brothers Distributors Inc

Pat Mitchell, UST Class A Operator

Pat Mitchell, UST Class B Global Operator

Karly Shafer, UST Class A Operator

Karly Shafer, UST Class B Global Operator Kathy Sindelar, UST Class B Operator Kyle Marx, UST Class A Operator

Kyle Marx, UST Class B Global Operator RaeDean Bartlett, UST Class B Global Operator

Tank Code	07	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3337	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	7000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				
Tank Code	08	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3338	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No

Report Created: 11/1/2022 Page [143] of [147]

Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				
Tank Code	09	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3339	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				
Tank Code	10	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3340	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				
Tank Code	11	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3341	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	12000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No

Report Created: 11/1/2022 Page [144] of [147]

		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				
Tank Code	12	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3342	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				
Tank Code	13	Tank Age	27	Tank Installed Date	04/01/1995	Tank Material	Fiberglass Reinforced Plastic	Piping Material	Flexible Plastic	Overfill Types	Ball Float Valve
Tag Number	3343	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	Double Walled	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Electronic Line Leak Detector	Piping Type	Pressurized	CP Met Types	Non-corrodible
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection	ELLD 0.2	Vapor Recovery	No
Capacity	2000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type	Franklin Fueling Systems/TS- LLD;Gilbarco- Veeder Root/TLS- 450				

## Facility Summary in Missoula County in the City of Seeley Lake

Location: SEELEY LAKE CONVENIENCE STORE 3072 MT Hwy 83
Seeley Lake, MT 59868 Missoula

Facility Code: 25483 Last Inspected On: 07/19/2021 Operating Permit Renewal Date: 08/22/2024

System Facility ID:32-09288

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Norman W and M Rose Baier 4066772004

Page [145] of [147] Report Created: 11/1/2022

## Owner/Operator: Norman W and M Rose Baier

Norman Baier, UST Class A Operator Norman Baier, UST Class B Operator Rose Baier, UST Class A Operator Rose Baier, UST Class B Operator

Tank Code	S1	Tank Age	35	Tank Installed Date	04/22/1987	Tank Material	Concrete	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	416	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/13/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	08/04/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	S2	Tank Age	35	Tank Installed Date	04/22/1987	Tank Material	Concrete	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	417	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	10/13/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	08/04/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					
Tank Code	S3	Tank Age	35	Tank Installed Date	04/22/1987	Tank Material	Concrete	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Ball Float Valve
Tag Number	418	Spill Test Date		Piping Installed Date		Tank Construction		Piping Construction	None	AST	Yes
Tank Status	Currently in Use	MLLD Test Date	07/19/2021	Sump Tightness Test Date		Catastrophic L.D Type 3.0	Mechanical Line Leak Detector	Piping Type	Pressurized	CP Met Types	
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date		Primary Tank Leak Detection		Primary Pipe Detection	MLLD Line Tightness Testing	Vapor Recovery	No
Capacity	8000	ATG Test Date		Line Tightness Test Date	08/04/2021	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					

Facility Summary in Missoula County in the City of TURAH

Report Created: 11/1/2022 Page [146] of [147]

Location: TURAH STORE and CAMPGROUND

13555 Turah Rd

TURAH, MT 59825-9775 Missoula

System Facility ID:32-04899

Facility Code: 25351 Last Inspected On: 09/09/2019 Operating Permit Renewal Date: 03/08/2023

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Turah Store and Campground LLC 4062589773

Operator Contact: Kathleen Marshall

Owner/Operator: Turah Store and Campground LLC

Jerry Kinney, UST Class B Operator Kathleen Marshall, UST Class A Operator Kathleen Marshall, UST Class B Global Operator Pamela Asbridge, UST Class B Operator

Tank Code	01	Tank Age	50	Tank Installed Date	04/18/1972	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	4007	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	07/17/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection		Vapor Recovery	No
Capacity	3000	ATG Test Date		Line Tightness Test Date	10/10/2007	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date				ATG Type					
Tank Code	02	Tank Age	50	Tank Installed Date	04/18/1972	Tank Material	Cathodically Protected Steel	Piping Material	Steel	Overfill Types	Flapper Valve
Tag Number	4008	Spill Test Date		Piping Installed Date		Tank Construction	Lined Interior/Impressed Current	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Impressed Current
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	07/17/2019	Primary Tank Leak Detection	Statistical Inventory Reconciliation	Primary Pipe Detection		Vapor Recovery	No
Capacity	1000	ATG Test Date		Line Tightness Test Date	10/10/2007	Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		<b>Overfill Test Date</b>				ATG Type					